



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 600577
Unit San Juan River
1-05-001-130

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

....., 1954

Well No. 1-0 is located 3470 ft. from N line and 220 ft. from E line of sec. 3

1.0, 1.0 (1/4 Sec. and Sec. No.) 20 (Twp.) 10 (Range) 1.0, 1.0 (Meridian)
San Juan River (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5517 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Sand 20-25 ft.

10-20-25 (Twp.) 10000 Depth 1000.

Run 1 3/4" to 3/4", 12.75 lb, Approx 12.75 lb, weld casing (122)

set at 10 ft with 1 1/2" and 30-70 Pumps, 2 1/2" 10-15, circulated

to surface. 12 hrs. 12 hrs. Approximate strength after 12 hrs.

12 hrs. Tested casing 100 ft.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company M. P. & S. Inc. Gas Co.

Address San Juan

San Juan, New Mexico

By

Title Geological Survey