

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

RECEIVED
SANTA FE, NM 87505

FEB - 6 1998

OIL CON. DIV.
DIST. 3

WELL API NO.

30-039-07692

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

E-289-31

7. Lease Name or Unit Agreement Name

009257

San Juan 29-6 Unit

8. Well No.

SJ 29-6 Unit #15

9. Pool name or Wildcat

Blanco Mesaverde 72319

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN A WELL BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

017654

2. Name of Operator

Phillips Petroleum Company

3. Address of Operator

5525 Highway 64, NBU 3004, Farmington NM 87401

4. Well Location

Unit Letter K : 1657 Feet From The South Line and 1650 Feet From The West Line

Section 2 Township 29N Range 6W NMPM Rio Arriba County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Remove sliding sleeve and packer ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In January 1997 the Lewis Shale pay was added to the existing Mesaverde interval during a side track procedure. A packer and sliding sleeve were placed in the tubing across the Lewis Shale interval for testing. The packer and sliding sleeve have been removed as follows:

2/3/98

MIRU Big A #29. Closed sliding sleeve and set plug in "F" nipple. ND WH. Installed BPV & NU BOPs. Unseat packer and POOH w/packer and sliding sleeve. RIH w/2-3/8" tubing and landed @ 5644' with "F" nipple @ 5609'. ND BOPs and NU WH. PT tubing. Pumped off check. RD & MO. Turned well back over to production department 2/4/98

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Patsy Clugston

TITLE

Regulatory Assistant

DATE

2-4-98

TYPE OR PRINT NAME

Patsy Clugston

TELEPHONE NO. 505-599-3454

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE

FEB - 6 1998

CONDITIONS OF APPROVAL, IF ANY: