Per m	9-40-1
Chay	1963)

UNITED STATES

orm 9-5-1 May 1963)	DEPARTMENT OF THE INTERIC		SF 079857
SI SI	UNDRY NOTICES AND REPORTS C	N WELLS	. IS INDIAN, ALIGHTEE OR TRIBE NAME
(Do not use	Use "APPLICATION FOR PERMIT— for such pro-) jpogalary	, UNIT AGEEEMENT NAME
OIL CAS	all TX OTHER		San Juan 29-5 Unit
NAME OF OPERAT			San Juan 29-5 Unit
	Natural Gas Company	ì	B. WELL NO.
P.O. Box. Location of WEI See also space 1 At surface	990 Farmington, New Mexic	O State requirements.	58 10. FIELD AND POOL, OR WITHCAT Basin Dakota 11. Sec. T., R., M., OR BEK. AND SURVEY OR ALEA
	800' S - 1500'W		Sec. 30-T29N-R5W N.M.P.M. 12. COUNTY OF PARISH 16. STATE
14. PERMIT NO.	15. ELEVATIONS (Show whether DE	r, RI, GR, etc.)	1
14. 150.311	6462' GL		Rio Arriba New Mexic
16.	Check Appropriate Box To Indicate 1	Nature of Notice, Report, or O	her Data
10.	NOTICE OF INTENTION TO:	SUESEQUE	ENT REPORT OF:
TEST WATER S FRACTURE THE SHOOT OR ACH REPAIR WELL (Other)	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recompleted and the second of the partiagent dates.)	of multiple completion on Well etion Report and Log form.) including estimated date of starting any
7 26 72	Reached intermediate casing	depth of 3668'. R	an 113 joints 7",
•	minutes. Top of cement at	2500'.	
3 - 30 - 72	T.D. 7875'. Ran 256 joints duction casing; 7865' set a Cemented with 653 cubic fee cement at 3260'.	et cement. W.O.C.	18 hours. Top of
4-5-72	P.B.T.D. 7867'. Perfd. 773 7816-22 with 18 SPZ. Frack gallons water. Dropped 4 s 5250 gallons water.	14-26, 7760-66, 77 8 c. with 48,000# 40/ sets of 18 balls ea	0-86, 7798-7804, 60 sand and 49,980 ach. Flush with
			RECEIVED
18, I hereby cy	tily that the foregoing is true and correct	Datroleum Fngineer	APR 1 2, 1972, 7

(This space for Federal or State office use) APPROVED BY _______ CONDITIONS OF APPROVAL, IF ANY:

DARE

APR 11 1972