| DEPARTM | | JNITED STATES SUBMIT IN TRIPLICATE. MENT OF THE INTERIOR (Other Instructions on reverse side) EOLOGICAL SURVEY | | Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL VO. NM - 10431 | | |
|---|----------------------------------|--|---|---|---|--|
| (Do not use | this form for proposi | CES AND REPORTS On the deepen or plug better to the FOR PERMIT—" for such pro- | ck to a different reservoir. | 6. IF INDIAN, ALLOTTE | E OR TRIME NAME | |
| OIL GAS WELL X OTHER | | | | 7. UNIT AGREEMENT NAME | | |
| 2. NAME OF OPERATOR | | | | 8. FARM OR LEASE/NAME | | |
| Continental Oil Company | | | | Conoco 29-4 9. WELL NO. | | |
| 3. Address of OPERATOR 152 North Durbin, Casper, Wyoming 82601 | | | | 5 | | |
| 152 North Durbin, Casper, Wyoming 82601 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1710 FNL, 800 FEL | | | | 10. FIELD AND POOL, OR WILDCAT E. San Juan - Gallup Dakot | | |
| | | | | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA | | |
| 7 | | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) | | Sec. 12, T29N, R4W | | |
| 14. PERMIT NO. | | 7112' GR, 7124' KB | | Rio Arriba | New Mexico | |
| | | | | | Hew Heater | |
| 16. | Check App | propriate Box To Indicate No | iture of Notice, Report, or C | Other Data | | |
| NOTICE OF INTENTION TO: | | | | UENT REPORT OF: | | |
| FRACTURE TREA | (Note: Report | | | | REPAIRING WELL ALTERING CASING ABANDONMENT* Experses 6/14/74 Sults of multiple completion on Well ompletion Report and Log form.) | |
| proposed wor nent to this w | k. If well is direction | ations (Clearly state all pertinent ally drilled, give subsurface location and the state all pertinent ally drilled, give subsurface location and testing. | details, and give pertinent dates, ns and measured and true vertica | including estimated dat il depths for all marker | e of starting any; ; and zones perti- | |
| | | | | | | |
| | | | | acrellien. | | |
| | | | | JUN 2 7 1974 | | |