UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*

Form approved. Budget Bureau No. 42/R1424. 5. LEASE DESIGNATION AND SEMAL NO.

NM 03040-A

						·	
SUN	1DRY	NOTICES	AND	REPORTS	ON	WELLS	5

11.	INDIA	N, A	LI.	OTI	EE,	()1(Ŧ	H I	R	ю	NΑ	MI	E

(Do not use this form fo	or proposals to drill or to deepen or plug back to a different reservoir. APPLICATION FOR PERMIT " for such proposals.)	
I. OIL CAS X	THER	7. UNIT AGREEMENT NAME San Juan 29-6 Unit
2. NAME OF OPERATOR Northwest Pipelin	ne Corporation	8. FARM OR LEASE NAME San Juan 29-6 Unit
P.O. Box 90, Fari	nington, New Mexico ceation clearly and in accordance with any State requirements.*	9. WELL NO. 46A 10. FIELD AND POOL, OR WILDCAT
At surface 940*	Blanco Mesa Verde 11. Sic., T., R., M., OR REE. AND SURVEY OR AREA	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	Sec. 27, T29N, R6W 12. COUNTY OF PARISH 13. STATE
	6383' Gr	Rio Arriba NM
16. Ch	ack Appropriete Box To Indicate Nature of Natice Report	or Other Desta

NOTICE OF I	NIENIION IO.	SUBSEQUENT REPORT OF.					
TEST WATER SHUT-OFF	PULL OR ALTER CASING	<u> </u>	WATER SHUT-OFF	REPAIRING WELL	l		
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT X	ALTERING CASING			
SHOOT OR ACIDIZE	ARANDON*		SHOOTING OR ACIDIZING X	ABANDONMENT*			
REPAIR WELL	CHANGE PLANS		(Other)	· ·- · · · · · · · · · · · · · · 	i		
(Other)			(Note: Report results of mu Completion or Recompletion	ultiple completion on Wel Report and Log form.)	1		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Squeezed top of liner w/100 sks Cl. "B" w/2% CC. 12--6-76

12-7-76 Tested to 3500 PSI, held OK. Spotted 500 gal 7 1/2% HCl. Ran GR-CC log and perfed from 5070' to 5618' w/22 shots. Pumped 1000 gal 7 1/2% HCl w/35 ball sealers. Fraced w/70,000 gal water and 60,000 # 20/40.

12-10-76 Landed 178 jts. (5597°) 2 3/8", 4.7#, J-55, EUE tubing at 5609° . Shut well in for test.





DEC 14 1976

U. S. GEOLOGICAL SURVEY DURANGO, COLO.

18. I hereby certify that the foregoing is true and offsect SIGNED	TITLE	Production Engineer	DATE	12/13/76
(This space for Federal or State office use)				
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE _	0 V	DATE	

*See Instructions on Reverse Side