Form 9-331 (May 1963)	UNITED STATES DEPARTMENT OF THE INTERI GEOLOGICAL SURVEY	SUBMIT IN TRIPLICATE* (Other instructions on reverse side)	Form approved. Budget Bureau No. 42-R1424 5. LEASE DESIGNATION AND SERIAL NO. SF 080146
SUI	NDRY NOTICES AND REPORTS (s form for proposals to drill or to deepen or plug I Use "APPLICATION FOR PERMIT—" for such p	ON WELLS back to a different reservoir. roposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL GAS X OTHER 2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME San Juan 29-6 Unit 8. FARM OR LEASE NAME
Northwest Pipeline Corporation 3. Address of Operator			San Juan 29-6 Unit 9. WELL NO.
P.O. Box 90, Farmington, New Mexico 87401 4. Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1530 * FNL & 895 * FWL			7A 10. FIELD AND FOOL, OR WILDCAT Blanco Mesa Verde 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whether Di		Sec. 34, T29N, R6W 12. COUNTY OR PARISH 13. STATE
16.	Check Appropriate Box To Indicate N		Rio Arriba N.M. Other Data
	NOTICE OF INTENTION TO:		UENT REPORT OF:
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED proposed work, nent to this work	MULTIPLE COMPLETE ABANDON* CHANGE PLANS OR COMPLETED OPERATIONS (Clearly state all pertine) If well is directionally drilled, give subsurface local	(Note: Report result: Completion or Recomp	REPAIRING WELL ALTERING CASING SURFACE ABANDONMENT* S of multiple completion on Well detion Report and Log form.) , including estimated date of starting an all depths for all markers and zones pert
3–18–77	MOL & RU. Spud at 1:30 PM 9 5/8", 32.3#, H-40, casing sks. C1. "B" w/3% CC. and 1 WOC.	g set at 229¹ KB. Cen	mented with 125
3-19-77	Tested surface csg. to 600	PSI for 30 minutes,	held OK.
		an Maria	
			MAR 2 5 1977
			U. A. COMORCAL SURVEY 14 P. COLO.