CONDITIONS OF APPROVAL, IF ANY:

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Dec 1973	Budget Bureau No. 42–R1424	
UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 080180 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do rot use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 29-6 Unit 8. FARM OR LEASE NAME	
1. pil gas well other	San Juan 29-6 Unit 9. WELL NO.	
2. NAME OF OPERATOR Northwest Pipeline Corporation 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Blanco Mesa Verde	
P 0. Box 90, Farmington, New Mexico 8740] 4. LCCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 pelow.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 9 T29N R6W	
AT SURFACE: 820' FSL & 980' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE New Mexico	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD)	

reser/cir. Use Fo	rm 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil	gas 🗓 other	San Juan 29-6 Unit
well L	well LAI other	9. WELL NO.
2. NAME OF	OPERATOR	64 A
	t Pipeline Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS	OF OPERATOR	Blanco Mesa Verde
	90, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
pelow.)	N OF WELL (REPORT LOCATION CLEARLY, See space 17 ACF: 820' FSL & 980' FEL	AREA Sec 9 T29N R6W
AT SURFA AT TOP F AT TOTAL	PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE New Mexico
		14. API NO.
	PPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
	OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6765 GR
•	R APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER FRACTURE TE		
SHOOT OR A		
REPAIR WELL		(NOTE: Report results of multiple completion or zone
PUL_ OR ALT		change on Form 9-330.)
MULTIPLE CO CHANGE ZON	–	
ABANDON*	n n	
(other)	"Spud"	
including	E PROPOSED OR COMPLETED OPERATIONS (Clearly state astimated date of starting any proposed work. If well is deland true vertical depths for all markers and zones pertiner. Spudded 12-1/4" surface hole @ 1245 his csg set @ 218". Cmted w/ 125 sks. Cintrology 1730 hrs. WOC 12 hrs. Pressure tested csg to 60	irectionally drilled, give subsurface locations and to this work.)* rs. Drld to 233' & ran 9-5/8" irc cmt to surface. Plug down
Subsurface Sa	nfety Valve: Manu, and Type	Set @ Ft.
13. Thereby o	ertify that the foregoing is true and correct	
SIGN ED	TITLE Production Cl	erk_ _{DATE} June 7, 1978
	(This space for Federal or State off	ica use)
ADDUOUED BY	TITLE	DATE : 为在中国财富 [7]

JUN 8 1978