## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

	Budget Bureau No. 42-R1424
	5. LEASE SF 080180
·	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
nt	7. UNIT AGREEMENT NAME San Juan 29-6 Unit
—	8. FARM OR LEASE NAME San Juan 29-6 Unit
	9. WELL NO. 39A
	10. FIELD OR WILDCAT NAME Blanco Mesa Verde
,	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 22 T29N R6W
	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
-	14. API NO.
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6680 GR

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a differe reservoir. Use Form 9–331–C for such proposals.) gas (X) well other 2. NAME OF OPERATOR Northwest Pipeline Corporation 3. ADDRESS OF OPERATOR P.O. Box 90, Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1650' FSL & 960' FEL AT TOP PROD. INTERVAL: same AT TOTAL DEPTH: same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multiple completion or PULL OR ALTER CASING change on Form 9 -330.) . MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other) "summary" 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* Spudded 12-1/4" surface hole @ 1600 hrs. Drld 12-1/4" hole to 210' & ran 4 jts (183') of 9-5/8" csg set @ 195'. Cmted w/ 125 sks. Circ 3 bbls cmt. Plug down 2200 hrs. 4-12-78 Pressure tested csg to 600 psi for 30 min, held OK. 4-15-78 Ran 93 jts (3888') of 7", 20# csg set @ 3900'. Cmted w/ 100 sks 65-35 poz & 30 sks C1"B". Plug down 0900 hrs 4-15-78. Cmt top by temp survey 3200'. 4-17-78 Ran 68 jts (2160') of 4-1/2", 10.5# csg liner set from 5967' to 3807'. Cmted w/ 210 sks C1"B", rev out 20 bbls. Plug down 0715 hrs. Pressure tested to 3500# for 30 min. Spotted 500 gal 7½% HCl. Perfed 30 holes 5366' to 5864'. Acidized w/ 1000 gal 7½% HCl & dropped 50 balls. Fraced w/ 100,000# 20/40 sand. Frac job complete 0500 hrs 4-18-78. 4-18-78 Ran 188 jts (5856') of 2-3/8", 4.7# tbg landed @ 5868', 4-19-78 Pumped out expendable check. Rig released 0600 hrs, Subsurface Safety Valve: Manu. and Type Set @ 18. I hereby certify that the foregoing is true and correct Production Clerk April 20, 1978 DATE (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: ARR 24 1978

IL S. GEOLOGICAL SURVEY See Instructions on Re DURANGO, COLO.