

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well
2. NAME OF OPERATOR
AMOCO PRODUCTION COMPANY
3. ADDRESS OF OPERATOR
501 Airport Drive Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
790' FSL x 1630' FWL, Section 9,
AT SURFACE: T-29-N, R-4-W
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: | | SUBSEQUENT REPORT OF: | |
|--------------------------|--------------------------|-----------------------|--------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | | <input type="checkbox"/> |
| (other) | Perf & Frac | | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- Completion operations commenced on 11/29/78. Tripped in with tubing and bit. Cleaned out to 3902' PBD. Pressure tested casing to 3400 psi; held OK. Perforated 3803-3820' with 2 SPF. Fraced with 59,500 lbs. sn and 33,750 gallons frac fluid. Set retrievable bridge plug at 3770'. Perforated 3535-3724' with 2 SPF. Fraced second stage with 70,000 lbs. sand x 37,500 gallons frac fluid. Tripped in with tubing and retrievable tool. Tagged sand 3710'. Cleaned out and recovered bridge plug. Production tubing landed at 3826'.

Completion rig released on 12/2/78.

Subsurface Safety Valve: Manu. and Type _____ Ft.

18. I hereby certify that the foregoing is true and correct


SIGNED _____ TITLE Dist. Adm. Supvr. DATE 12/6/78

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

5. LEASE SF-079757A	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME San Juan 29-4 Unit	
8. FARM OR LEASE NAME	
9. WELL NO. 22	
10. FIELD OR WILDCAT NAME East Blanco Pictured Cliffs	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SE/4 SW/4 Section 9, T-29-N, R-4-W	
12. COUNTY OR PARISH Rio Arriba	13. STATE NM
14. API NO. 30-039-21844	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 6833' GL, 6843' KB	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)



DEC 07 1978