

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other
2. NAME OF OPERATOR  
Northwest Pipeline Corporation
3. ADDRESS OF OPERATOR  
P.O. Box 90, Farmington, New Mexico 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1160' FSL & 950' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

## SUBSEQUENT REPORT OF:

- ☒  
☐  
☐  
☐  
☐  
☐  
☐  
☐

## 5. LEASE

SF-080069

## 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## 7. UNIT AGREEMENT NAME

San Juan 29-5 Unit

## 8. FARM OR LEASE NAME

San Juan 29-5 Unit

## 9. WELL NO.

#97

## 10. FIELD OR WILDCAT NAME

Blanco Pictured Cliffs

## 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 15 T29N R5W

## 12. COUNTY OR PARISH

Rio Arriba

## 13. STATE

New Mexico

## 14. API NO.

30-039-21393

## 15. ELEVATIONS (SHOW DF, KDB, AND WD)

6818' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

June 18, 1980 - Ran GR/CCL log and correlated to FDC/GR Log. Perfed 16 holes from 3782' to 3854'. Fraced with 5000 gal pad water (2-1/2# FR/20/1000 gal) followed with 50,000# 10/20 sand @ 1/2 - 1 ppg. MIR - 31 BPM; MIP 4000#; AIR 31 BPM; AIP 3600#. Frac job complete @ 1000 hrs. ISIP 500#, 5 min 400#; opened well to atmosphere to clean up at 1200 hrs. NOW WAITING ON IP TEST.

ACCEPTED FOR RECORD

JUN 27 1980

BY *[Signature]*

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

*[Signature]*  
Donna Brace

TITLE

Production Clerk

DATE

June 20, 1980

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MOCC