DEPARTMENT OF THE INTERIOR	5. LEASE SF 078917 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 29-5 Unit
1. oil gas well other 2. NAME OF OPERATOR Northwest Pipeline Corporation 3. ADDRESS OF OPERATOR P.O. Box 90, Farmington, N.M. 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1050' FNL & 1970' FEL AT TOP PROD. INTERVAL: Same as above AT TOTAL DEPTH: Same as above 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF Gracture TREAT Gractu	8. FARM OR LEASE NAME San Juan 29-5 Unit 9. WELL NO. #101 10. FIELD OR WILDCAT NAME Gobernador PC/ Blanco MV 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 26, T29N, R5W 12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO. 30-039-22484 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6904' GR
PULL OR ALTER CASING	firectionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertined 4-6-81 Did not circulate cmt behind 7" of cmt at 3005'.	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED Donna D Brace Production Cl	lerk DATE 4-21-81

__ TITLE __ MNOCC.

APR 29 1981

_____ DATE _

ACCEPTED FOR RECORD

(This space for Federal or State office use)