Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe New Mexico 87504-2088 Revised 1-1-89

WELL API NO.

30-039-24610

P.O. Drawer DD,	P.O. Drawer DD, Artesia, NM 88210				5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410					STATE	FEE	
1000 Rio Brazos F	Rd., Aziec, NM 87410		6. State Oil & Gas Lease No. E-289-45				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)							
				7. Lease Name o	r Unit Agreement Name		
1. Type of Well:		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
MEIT [GAS WELL X	OTHER		San Tua	n 29-6 Unit		
2. Name of Open	ator			8. Well No.	11 22-0 OILL		
Phillips	Petroleum Comp	any		231			
3. Address of Operator 300 W. Arrington, Suite 200, Farmington, N.M. 87401					9. Pool name or Wildcat		
4. Well Location	arrington, Suite	200, Familingle	on, N.M. 87401	Basin F	<u>ruitland Coal</u>	Gas	
Unit Lett	ter <u>A</u> : <u>826</u>	Feet From The north	Line and 94	7 Feet From	m The east	Line	
Section	36	Township 29N	Range Galler	NMPM	Rio Arriba	County	
		////	w whether DF, RKB, RT, GR, etc.)				
		6438'			<u> </u>		
11.	_		idicate Nature of Notice,	-			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REME	DIA PORK	LUG AND BANDON	N REMEDIAL WORK		ALTERING CASING		
	BANDON APRI 2 1	COHANGE FLANS	COMMENCE DRILL	ING OPNS	PLUG AND ABAND	ONNAENT	
PULL OR ALTER	CASING APRIZE	990			FEOG AND ABAND	DIAIMEIA I	
	"OIL CON.	DIV.	CASING TEST AND	CEMENT JOB			
OTHER:	DIST.		U OTHER:	· · · · · · · · · · · · · · · · · · ·			
12. Describe Propo work) SEE RU		s (Clearly state all pertinent	t details, and give pertinent dates, in	scluding estimated date	of starting any proposed		
3-08-90:	Smidded 12-1//	" hole at 11.30) p.m. Set 9-5/8"	ዓ ና ። የ ፈ55 የምደር	' casing at		
J-00-70.	250' w/250 sx	Class "G". 3% (CaCl ₂ & 1/4# /sx gel	l flakes. Bu	mned nlug		
	w/500 psi. Ci	rc 100 sx, WOO	C 13.25 hrs.	- 1201.001	miner brown		
		_	,				
3-12-90:			at 3144' with 500 s			es	
			/4#/sx gel flake. (& lines, set casing			.d	
	rig at 12:30 p		e inles, set cashi	8 strbs 0/24,	ooo, Refease	:u	
	116 de 11.00 p						
4-04-90:			t and pressure teste				
	rams.wellhead	and casing to	200 psi for 10 min		or 30 min,		
				. ^^^			
	all tested ok.		sets of pipe rans	to 200 psi fo			
	all tested ok. 2500 psi for 3	0 min, held ok.	sets of pipe rams t	to 200 psi fo 			
I hereby certify that	all tested ok.	o min, held ok.	sets of pipe rans to	-	or 10 min and		
I hereby certify that	all tested ok. 2500 psi for 3	o min, held ok.	sets of pipe rams t	-	or 10 min and	00	
	all tested ok. 2500 psi for 3 the information above is true and	o min, held ok.	sets of pipe rans to	-	or 10 min and	00	
SIGNATURE	all tested ok. 2500 psi for 3 the information above is gree and	o min, held ok.	sets of pipe rans to	-	or 10 min and	00	
SIGNATURE TYPE OR PRINT NAM (This space for State	all tested ok. 2500 psi for 3 the information above is gree and	of min, held ok.	sets of pipe rans to	. & Pro.	or 10 min and		

OR CON. DIV.

A PAR

DYARE I HAVE M Smit larged