

F

30-039-24847

07-23-90

F. Loc. 1479/S; 1620/W Elev. 6697 GL Spd. _____ Comp. _____ TD. _____ PB _____
 Casing S. _____ @ _____ W _____ Cu. ft. _____ Cu. ft. _____ Cu. ft. _____
 Csg. Perf. _____ Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NitD	X	Well Log	TEST DATA							
Ojo Alamo		C - 103		Plot	X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C - 104		Electric Log								
Fruitland				C - 122								
Pictured Cliffs		Ditr		Dfa								
Chacra		Datr		Dac								
Cliff House												
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrada												
		Acres W/320										

P
o
o

BasinFrCoal Co. RA S 23 T 29N R 06W UK Oper. Phillips Petroleum Co. Lse. San Juan 29-6 Unit No. 251

San Juan 29-6 Unit #251

K-23-29N-06W

PHILLIPS PETROLEUM CO.