UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notic	ces and Reports on Wells		
		5.	Lease Number SF-078945
CAS		6.	If Indian, All. or Tribe Name
		7.	Unit Agreement Name
Name of Operator BURLINGTON RESOURCES	GAS COMPANY		San Juan 29-7 Unit
3. Address & Phone No. of Operator		8.	
PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.	API Well No. 30-039-25667
1. Location of Well, Footage, Sec. 1795'FSL, 1510'FWL, Sec.1, T-			Field and Pool Blanco Mesaverde County and State
R-10720			Rio Arriba Co, NM
X Subsequent Report Final Abandonment Describe Proposed or Compl	Plugging Back Non- Casing Repair Wate Altering Casing Conv X Other -	r Shut o	Fracturing ff
J-55 8RD ST&C li "B" 65/35 poz w Tailed w/117 sx Gilsonite, 0.3%	3'. Circ hole clean. TOOH. Then, set @ 6927'. Top of lnr @ /6% gel, 0.25 pps Flocele, 5 Class "B" 50/50 poz w/2% gel fluid loss (155 cu.ft.). Disto surface. ND BOP. NU WH. R	9 4433'. pps Gils , 0.25 p place w/	Cmtd w/160 sx Class onite (296 cu.ft.). ps Flocele, 5 pps 65 bbl wtr. Reverse
	1981 - 660AL 1911 1981 - 1		
(// 8	foregoing is true and correct Title Regulatory Administ:		e 6/19/97
(This space for Federal or State	Office use) Title	Date A	CCEPTED FOR RECOR
CONDITION OF APPROVAL, if any:			IIIN 0 0 1007

JUN 23 1997