Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

•	 	• • •
_	 	

SF-078960

SUNDRY	NOTICES	AND	REPORTS	ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE - Oth	er instructions o	n reverse side	00	7. If Unit or C.	A/Agreement, Name and/or No.		
. Type of Well X Gas Well Other			San Juan 2 8. Well Name				
Name of Operator Phillips Petroleum Company			. // s	SJ 29-6 Un			
First ps rectoreum company		3b. Phone No. (include area.	9. API Well No. Phone No. (include area soile) 30-039-26342				
5525 Highway 64, NBU 3004, Farmington,	NM 87401	505-599-3454		10. Field and I	Pool, or Exploratory Area		
Location of Well (Footage, Sec., T., R., M., or Survey De	escription)			Basin Dako Blanco Mes			
Unit 0, 1190' FSL & 1850' FEL Section 35, T29N, R6W		II. County or					
				<u>Rio Arriba</u>	a, <u>NM</u>		
12. CHECK APPROPRIATE	BOX(ES) TO IN	DICATE NATURE OF NOTIC	CE, REPORT, C	OR OTHER DA	ATA		
TYPE OF SUBMISSION		TYPE	OF ACTION				
Notice of Intent	Acidize	Deepen [Production (Start/Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamation		Well Integrity		
X Subsequent Report	Casing Repair	New Construction	Recomplete		X Other 4-1/2"		
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily	Abandon	<u>casing report</u>		
	Convert to Injection	on Plug Back	Water Dispo	sal			
rollowing completed. Final Abandonment Notice determined that the final site is ready for final inspection.) RIH w/6-1/4" bit. D/O 40' cement to Circ. hole. RiH w/4-1/2" 11.6# I-8 sx (347 cf - 61.79 bbl slurry) Class Gilsonite, 0.3% CD-32, 0.7% FL-52. 5#/sx Gilsonite, 0.3% FL-25 displace 2nd stage - lead - 85 sx (164 cf - CSE, 1/4#/sx Cello-flake, 5#/sx Gilbbl slurry) Type III, 1% CaCl2, 1/47/16/00. Had 50 bbl fluid to surface ND BOP, Set slips and cut off casin on DK completion report.	o shoe @ 3840 0 casing and s H 35/65 POZ Tail - 50 sx ed w/121.5 bb 29.20 bbl slu sonite, 0.4% #/sx Cello-fl e, no cement.	'. Drilled ahead to set @ 7881'. RU to . 6% Bentonite, 10#/. (63 cf - 11.21 bbl . RU to . Plug down RY) Type III, 35/65 FL-25, 0.02#/sx Stat ake. Displaced w/79	7881' (TD cement. P sx CSE, 1/ slurry) Cl Dropped D POZ, 6% B cic free.). TD redumped 1st 4#/sx Cel ass H, 1/d V tool & dentonite, Tail - 50 Plug do	ached 7/16/00. stage Lead - 155 lo-flake, 5#/sx 4#/sx Cello-flake, opened. Pumped 3% KCL, 10#/sx sx (70 cf - 12.46 wn @ 2215 hrs on		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		Title					
Patsy Clugston		" "		cory/Prora	tion Clerk		
Talsy Mg"		Date 8/3/0					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by	his notice does not				Date 2001		
Conditions of approval, if any, are attached. Approval of the certify that the applicant holds legal or equitable title to the which would entitle the applicant to conduct operations thereon.	bject lease			RATE OF LEFT OF			
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1 States any false, fictitious or fraudulent statements or representation	212, makes it a crimons as to any matter w	ne for any person knowingly and ithin its jurisdiction.	d willfully to ma	ake to any depa	artment or agency of the Unite		