Submit 3 Copies To Appropriate Dist		State of New Mexico Energy, Minerals and Natural Resources		Form C-103	
District I 1625 N. French Dr., Hobbs, NM 8724 District II	10	OIL CONSERVATION DIVISION		Revised March 25, 1999 WELL API NO. 30-039-76558	
811 South First, Artesia, NM 87210 District III		2040 South Pacheco		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 874		Santa Fe, NM 87505		STATE FEE X	
District IV 2040 South Pacheco, Santa Fe, NM 87505		6. State Oil & Gas Lease No.			
TOO NOT USE THIS FORM FOR E	OTICES AND REPORTS ON PROPOSALS TO DRILL OR TO THE PER APPLICATION FOR PERMIT" (FORM CONTINUED OF THE PERMIT OF TH		7. Lease Name or Unit	Agreement Name:	
2. Name of Operator			8. Well No.		
Phillips Petroleum Company 017654			SJ 29-5 Unit #13M		
3. Address of Operator 5525 Highway 64, NBU 3004, Farmington, NM 87401			9. Pool name or Wildcat Blanco MV - 72319 & Basin DK - 71599		
4. Well Location					
Unit Letter0	: 1309' feet from the	South line and	1349' feet from the	<u>East</u> line	
Section 30	Township 29N	Range 5W		unty Rio Arriba	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 6649' GL					
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK		REMEDIAL WORK		TERING CASING	
TEMPORARILY ABANDON	☐ CHANGE PLANS ☐	COMMENCE DRILLI		UG AND BANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		, <u>.</u>	
OTHER:		OTHER:	Spud Report		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
3/14/01 MIRU Key Energy #47. Drilled 12-1/4" hole @ 2100 hrs 3/14/01. Drilled ahead to 335'. RIH w/9-5/8", 32.3# H-40 casing and set @ 333'. RU to cement. Pumped 10 bbls mud clean and 10 bbls dye water ahead of 220 sx (310 cf - 55.20 bbl slurry) Type 3, 2% CaCl2, 0.25#/sx Cello-flake. Displaced w/24 bbls H20. Plug down @ 0655 hrs 3/15/01. Circ. 10 bbls good cement to surface. WOC.					
NU WH & NU BOP. PT rams, manifold and casing to 200 psi and then 1500 psi. Good test.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE / MAN	0				
	sy Clugston	DAN W B CAC	Telephone N	o. 505-599-3454	
(This space for State use) OFIGHERAL STANE	D BY CHAPLE T. PENNIN	DETUIT OIL & GV2	DATE	MAR 21 2001	

TITLE

DATE