



**Key Energy Services, Inc.**

Four Corners Division  
5651 US Highway 64  
P.O. Box 900  
Farmington, NM 87499

Phone: 505-327-4935  
Fax: 505-327-4962

June 21, 2001

Rig No. 47

Phillips Petroleum Company  
5525 Hwy 64 NBU 3004  
Farmington, NM 87401

Attn: Patsy Clugston




This letter is to certify that Key Energy Services, Inc., did run deviation surveys at the listed depths on the San Juan 29-6 70B well in S29-T29N-R06W, in Rio Arriba, county, New Mexico.

Depth	Deviation	Depth	Deviation
156'	$\frac{1}{4}^{\circ}$	3191'	$1^{\circ}$
340'	$\frac{3}{4}^{\circ}$	3543'	$\frac{1}{2}^{\circ}$
654'	$\frac{1}{4}^{\circ}$	3992'	$1^{\circ}$
1172'	$\frac{3}{4}^{\circ}$	4490'	$\frac{3}{4}^{\circ}$
1671'	$\frac{1}{2}^{\circ}$	4983'	$1^{\circ}$
2166'	$\frac{1}{2}^{\circ}$	5481'	$1\frac{1}{2}^{\circ}$
2667'	$\frac{1}{4}^{\circ}$	5789'	$\frac{3}{4}^{\circ}$

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith  
Drilling contract manager



Notary Public

My commission expires:

6/26/02