Ferm 9-331 (May 1963)

## UNITED STATES UNITED STATES SUBMIT IN TRIPLICATES DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

Form approved,
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SF - 078284

GEOLOGICAL SURVEY

	15514 11051650 1110 5			6. IF INDIAN, ALLOTTES	E OR TRIBE NAME	
	IDRY NOTICES AND R form for proposals to drill or to d Use "APPLICATION FOR PERMI					
1.				7. UNIT AGREEMENT NA	7. UNIT AGREEMENT NAME	
OIL GAS X OTHER				San Juan 29	San Juan 29-6 Unit	
2. NAME OF OPERATOR				8, FARM OR LEASE NAM	8. FARM OR LEASE NAME	
Northwest Pipeline Corporation				San Juan 29	San Juan 29-6 Unit	
3. ADDRESS OF OPERATOR				9. WELL NO.		
P.O. Box 90 Farmington, New Mexico 87401				43	43	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface					Blanco Mesa Verde	
Rt Bullace				11. SEC., T., R., M., OR I		
36501				SURVEY OR AREA	SER. AND	
1620. 1	FNL 1650' FEL			0 06 maoy	D(11 111/D)1	
			~	Sec 26 T29N		
14. PERMIT NO.		Show whether DF, RT, GR, et	ž.)	12. COUNTY OR PARISH	1	
	6404'	DF		Rio Arriba	New Mexico	
16.	Check Appropriate Box 7	o Indicate Nature of	Notice, Report, c	or Other Data		
	NOTICE OF INTENTION TO:	1		SEQUENT REPORT OF:		
TEST WATER SHUT-O	PCLL OR ALTER CAS	ING TO THE	ATER SHUT-OFF	REPAIRING	WELL.	
FRACTURE TREAT	MULTIPLE COMPLET	<u>                                     </u>	ACTURE TREATMENT	ALTERING C.		
SHOOT OR ACIDIZE	ABANDON*		HOOTING OR ACIDIZING	Dike Constructio		
REPAIR WELL	CHANGE PLANS	(0	(Note: Report res	ults of multiple completion		
(Other)			Completion or Reco	ompletion Report and Log for	rm.)	
Constr	ucted 25' x 33' x 2'	dike around con	densate tank.			
See at	tached drawing.			OIL C	3	
SIGNED R.E.	t the foregoing is true and correct  Fielder js eral or State office use)	TITLE Sr. Prod	luction Engine	eer DATE 8-23	3-76	
	DDDOVAL IF ANY.	*******		DAIN		