

District I
P.O. Box 1980, Hobbs, NM
District II
P.O. Drawer DD, Artesia, NM 88211
District III
1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND SUPPLY TO
SANTA FE OFFICE
DEPUTY OIL & GAS INSPECTOR

SEP 11 5 1995

PIT REMEDIATION AND CLOSURE REPORT

Operator: Phillips Petroleum Company Telephone: (505) 599-3460
Address: 5525 Hwy. 64, NBU 3004, Farmington, NM 87401
Facility Or: San Juan 29-6 Unit #43 (MV)
Well Name _____
Location: Unit or Qtr/Qtr Sec SW NE Sec 26 T 29N R 6W County Rio Arriba
Pit Type: Separator X Dehydrator _____ Other Condensate Tank
Land Type: BLM X, State _____, Fee _____, Other _____

Pit Location: Pit dimensions: length 30', width 30', depth 5'
(Attach diagram) Reference: wellhead X, other _____
Footage from reference: 25
Direction from reference: 45 Degrees X East North X
of
_____ West South _____

Depth To Ground Water: Less than 50 feet (20 points)
(Vertical distance from X 50 feet to 99 feet (10 points)
contaminants to seasonal Greater than 100 feet (0 Points) 10
high water elevation of
ground water)

Wellhead Protection Area: Yes (20 points)
(Less than 200 feet from a private X No (0 points) 0
domestic water source, or; less than
1000 feet from all other water sources)

Distance To Surface Water: Less than 200 feet (20 points)
(Horizontal distance to perennial 200 feet to 1000 feet (10 points)
lakes, ponds, rivers, streams, creeks, X Greater than 1000 feet (0 points) 0
irrigation canals and ditches)

RANKING SCORE (TOTAL POINTS): 10

Date Remediation Started: N/A Dated Completed: _____

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____
Other _____

Remediation Location: Onsite _____ Offsite _____
(ie. landfarmed onsite, name and location of offsite facility)

General Description Of Remedial Action: N/A

Initial assessment of pit showed soils to be clean

at the surface and at three feet below pit bottom.

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit: Sample location Deepest part of pit. Sampled with a backhoe.

Closure Sampling:
(if multiple samples, attach sample results and diagram of sample locations and depths)

Sample depth 3 ft. below pit bottom

Sample date 7/9/93 Sample time -

Sample Results

Benzene(ppm) -

Total BTEX(ppm) -

Field headspace(ppm) 0

TPH 0

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE

4-13-94

SIGNATURE

Ed Hasely

PRINTED NAME
AND TITLE

Ed Hasely
Environmental Engineer

PIT NO	WELL NAME	U-S-T-K	PIT TYPE	RANK SCORE	CLOSURE STANDARD TPH (PPM)	DATE 1993	GROUNDWATER ENCOUNTERED Sub-Surf. Depth	SOIL TYPE	PIT TYPE	SAMPLE NO.	Organic Vapor Mtr (PPM)	Recoverable Pet. Hydro. (TPM)	EPA METHOD 8020 (PPB)				TOTAL BIEX	STATUS	
													Benzene	Toluene	Ethyl Benzene	Xylene			
PA030	SAN JUAN 29-6, #85	M272006	SEP	0	5000	7-09	NO	SM	EARTHEN	T1-7 T1-13 T1-17	533 423 87		9.1	0	67	0	27	94	TEST
PA040	SAN JUAN 29-6, #43-26	G292906	SEP	10	1000	7-09	NO	SC	EARTHEN	T1-8	0	0	0						CLOSE
PA041	SAN JUAN 29-6, #98	H262906	SEP	10	1000	7-09	NO	CL	EARTHEN	T1-7.5	1.2	7.5							CLOSE
PA042	SAN JUAN 32-8, #15	M243108	SEP	0	5000	7-12	NO	SC	EARTHEN	T1-3.5 T1-6	0.5 1.1		8.8						CLOSE
PA043	SAN JUAN 32-8, #20 NP	L043108	SEP			7-12	NO	SM/CL	EARTHEN	T1-1.5 T1-4	0.8 0.8		0						CLOSE
PA044	SAN JUAN 32-8, #25-33	B333208	SEP			7-12	NO	SM/SC	EARTHEN	T1-1 T1-4	0.5 0.8		13.5						CLOSE
PA045	SAN JUAN 32-8, #30-27	M273208	SEP			7-12	NO	SM	EARTHEN	T1-1.5 T1-4	0.8 0.8		10.1						CLOSE
PA046	SAN JUAN 32-7, #58	G183207	SEP			7-12	NO	OH/CL	EARTHEN	T1-5 T1-7 T1-13 T2-6 T2-11 T2-13	1858 691 100 2.1 1.1 1.1							REM	
PA047	SAN JUAN 32-7, #43	B213207	SEP	20	100	7-12	NO	OH/CL	EARTHEN	T1-5 T1-10	229 2.8		9.1						TEST
PA048	SAN JUAN 32-7, #5	H083107	SEP	20	100	7-12	NO	SM	EARTHEN	T1-2.5 T1-5	1.1 0		0						CLOSE
PA049	SAN JUAN 32-7, #5	H083107	BLOW	20	100	7-12	NO	SP	EARTHEN	T1-3.5	0		335						REM
PA050	SAN JUAN 29-5, #106 PM	H252905	SEP	0	5000	7-13	NO	CL/GM/SM	EARTHEN	T1-7 T1-10 T2-5 T2-11	607 617 5 18.6		610						TEST
PA051	SAN JUAN 30-5, #4	B333005	SEP	10	1000	7-13	NO	OL	EARTHEN	T1-1.5 T1-4	2 2.4		17.1						CLOSE
PA052	SAN JUAN 30-5, #11	L233005	SEP	10	1000	7-13	NO	SM	EARTHEN	T1-5	14		6.5						CLOSE
PA053	SAN JUAN 30-5, #32-26	A263005	SEP	0	5000	7-13	NO	SM	EARTHEN	T1-4	1.3		17.1						CLOSE
PA054	SAN JUAN 30-5, #8-11	B113005	SEP	10	1000	7-13	NO	SC	EARTHEN	T1-0.5 T1-9	0 0		5.6						CLOSE

ENVIROTECH Inc.

5796 US HWY. 64, FARMINGTON, NM 87401
(505) 832-0615

PIT NO: PA 40

C.O.C. NO: 2807

FIELD REPORT: SITE ASSESSMENT

JOB NO: 93167

PAGE No: 1 of 1

PROJECT: PIT ASSESSMENT
CLIENT: PHILLIPS
CONTRACTOR: ENVIROTECH INC.
EQUIPMENT USED: EXTENSION HOLE

DATE STARTED: 7-2-93
DATE FINISHED: 7-2-93
EIMRO. SPCLT: SC
OPERATOR: Garrett
ASSISTANT:

LOCATION: LEASE: SJ 29-6 WELL: 43-26 QD: 1650' N x 1650' E (G)
SEC: 26 TWP: 29N RNG: 6W PM: NJM CNTY: RA ST: NM PIT: Sopantoe
LAND USE: RANGE Less: 55 078284
SURFACE CONDITIONS: DPT

FIELD NOTES & REMARKS: PIT IS LOCATED APPROXIMATELY 25 FEET NE OF WELLHEAD.
CLOSURE STD: 1000 ppm TPH
RANKING SCORE: 10

PIT 30' x 30' x 5' Deep

No dark color or odor

SAMPLER

8' - No odor - Yellow/Green sand & clay.
SAMPLE for lab 418.1 @ 1410'

SAMPLE INVENTORY		
SMPL ID:	SMPL TYPE:	LABORATORY ANALYSIS:
T10 B'	GRAB	418.1

SCALE



0 10 20 FEET

SITE DIAGRAM

TEST HOLE LOGS:

TH#	TH#	TH#	TH#
SOIL TYPE	SMPL TYPE	SOIL TYPE	SMPL TYPE
1	2	3	4
5	6	7	8
9	10	11	12
13	14	15	16
17	18	19	20
21	22	23	24
25	26	27	28
29	30	31	32
33	34	35	36
37	38	39	40
41	42	43	44
45	46	47	48
49	50	51	52
53	54	55	56
57	58	59	60
61	62	63	64
65	66	67	68
69	70	71	72
73	74	75	76
77	78	79	80
81	82	83	84
85	86	87	88
89	90	91	92
93	94	95	96
97	98	99	100

SOIL TYPE: C - Clay, M - Sil, S - Sand, J - Gravel, Plasticity: L - Plastic, H - Hard, G - Gravel, P - Phos, A - Ash