



(SUBMIT IN TRIPPLICATE)

**UNITED STATES**  
**DEPARTMENT OF THE INTERIOR**  
**GEOLOGICAL SURVEY**

Land Office ... Santa Fe  
Lease No. ... 478399  
Unit ... San Juan 22-7  
14-38-01-567

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

, 19 58

February 1,

Well No. 62 is located 150 ft. from **N** line and 180 ft. from **E** line of sec. 22.

N. Sec. 22  
(1/4 Sec. and Sec. No.)      Twp. 7  
(Twp.)      Range  
(Range)      Meridian  
(Meridian)

Blanco  
(Field)      Rio Arriba  
(County or Subdivision)      New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 6493 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-18-58 Total depth 5964'. Ran 57 joints 5 1/2", 13.54, 4-55 casing (2014') from 3746' to 5964' with 125 sacks regular cement, 105 sacks pozzmix, 60 gal., followed by 50 sacks regular cement.

Held 1000# for 30 minutes.

Run of cement by temperature survey at 2746'.

RECEIVED  
 MAR 1 1958  
 U. S. GEOLOGICAL SURVEY  
 FARMINGTON, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ... El Paso Natural Gas Company

GENERAL SUPERVISOR MCANALLY

Address ... Box 1077

Farmington, New Mexico

By ...  
Title ... Manager, Engineering