Form Approved. Budge: Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR

| . LEASE | • | | |
|---------|-----|--|--|
| F 078 | 399 | | |

| UNITED STATES DEPARTMENT OF THE INTERIOR | 5. LEASE SF 078399 | | |
|---|---|--|--|
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | | |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAME | | |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | San Juan 29-7 Unit | | |
| reservoir, use runn 3-331-C for such proposals. | 8. FARM OR LEASE NAME | | |
| 1. oil gas k other | San Juan 29-7 Unit | | |
| Netr Tell Street | 9. WELL NO. | | |
| 2. NAME OF OPERATOR | 35A | | |
| EL PASO NATURAL GAS CO. | 10. FIELD OR WILDCAT NAME | | |
| 3. ADDRESS OF OPERATOR | Blanco Mesa Verde | | |
| BOX 990, FARMINGTON, NEW MEXICO 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T-29-N,R-7-W | | |
| below.) AT SURFACE:1750'S, 980'E | NMPM | | |
| AT TOP PROD. INTERVAL: | 12. COUNTY OR PARISH 13. STATE | | |
| AT TOTAL DEPTH: | San Juan New Mexico | | |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, | 14 . API NO. | | |
| REPORT, OR OTHER DATA | 15 FLEVATIONS (OLIOW DE VIDE AND AND | | |
| NEI ONI) ON OTHER DIM | 15. ELEVATIONS (SHOW DF, KDB, AND WD) | | |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | 6165 GL | | |
| TEST WATER SHUT-OFF | | | |
| FRACTURE TREAT | | | |
| SHOOT OR ACIDIZE | | | |
| REPAIR WELL | (NOTE: Report results of multiple completion or zone | | |
| PULL OR ALTER CASING MULTIPLE COMPLETE | change on Form 9-330.) | | |
| MULTIPLE COMPLETE | | | |
| ABANDON* | | | |
| (other) | | | |
| | : | | |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen | rectionally drilled, give subsurface locations and | | |
| 0/14/50 0 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | • | | |
| 8/14/78: Spudded well. Drilled surface hole | | | |
| Ran 5 joints 9 5/8", 32.3# H-40 sur | face casing, 218' set | | |
| at 229'. Cemented with 224 cu. ft. | cement. Circulated | | |
| to surface. WOC 12 hours; held 600 | 0#/30 minutes. | | |
| | | | |
| | \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ | | |
| | 2/2/2/ | | |
| | 65° COM. | | |
| | 1 2/10 04. 3 | | |
| | 1 1 00 51. | | |
| | OID D. | | |
| | RUG 28 1978 OIL CON: 73 | | |
| Subsurface Safety Valve: Manu. and Type | Set (1) Ft. | | |
| 18. I hereby certify that the foregoing is true and correct | | | |
| SIGNED TITLE Drilling Cler | k DATE 3846/78 | | |
| | | | |
| (This space for Federal or State offi | ce use) | | |
| APPROVED BY TITLE | DATE | | |
| CONDITIONS OF APPROVAL, IF ANY: | | | |
| | | | |
| | | | |
| ADOL TO ANNUAL TO POST OF | aug 2 5 1978 | | |
| *See Instructions on Reverse S | Ide Udd 8 0 1010 | | |