## UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF 078424A
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
SUNDAY NOTICES AND INCLUDING ON THEELO	San Juan 29-7 Unit
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🔽	San Juan 29-7 Unit
well well to other	9. WELL NO.
2. NAME OF OPERATOR	
EL PASO NATURAL GAS CO.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco M.V.
BOX 990, FARMINGTON, NEW MEXICO	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 24, T-29-N, R-7-W
below.) AT SURFACE: 2170'S, 790'E	NMPM 12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6247 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT  SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	•
CHANGE ZONES	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined 8/23/78: Spudded well. Drilled surface holes	nt to this work.)*  2. Ran 5 jcints 9 5/8", 32.3# H-40
surface casing, 225' set at 236'. Cemented was to surface. WOC 12 hours; held 600#/30 minut	vith 224 cu. ft. cement. Circulated tes.
	3 1978
Subsurface Safety Valve: Manu. and Type	Set @ COM. Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED TITLE Drilling Cle	rk DATE 8/24/78
(This space for Federal or State o	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE
COMBINIONS OF AFFINOTAL, II AITT.	1 1073