
UNITED STATES

UNITED STATES	5. LEASE 연기 원 원 원 원 원 원 원 원 원 원 원 원 원 원 원 원 원 원
DEPARTMENT OF THE INTERIOR	SF 078945 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	학식통에 전 원통를
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	SAN JUAN 29-7 UNIT
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas	SAN JUAN 29-7 UNIT
well well other	9. WELL NO.
2. NAME OF OPERATOR	
EL PASO NATURAL GAS CO.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	BASIN DAKOTA
BOX 289, FARMINGTON, NEW MEXICO	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA SEC. 29, T-29-N, R-7-W
below.)	NMPM = 9 P = 2 P P P
AT SURFACE: 945'N, 2300'E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	RIO ARRIBA NEW MEXICO
	14. API NO. 等异性的 电 引起形式
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6376' GL
TEST WATER SHUT-OFF	eri erika
FRACTURE TREAT	# # # # # # # # # # # # # # # # # # #
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple complet 1078
PULL OR ALTER CASING	change on Form 9–330.)
CHANGE ZONES	Series in the promote that the property
ABANDON*	YSVEUS ACAMONO OF THE PROPERTY
(other)	
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di 	e all pertinent details, and give pertinent dates,
measured and true vertical depths for all markers and zones pertinen	t to this work.)*
10/17/78: T.D. 3383'. Ran 83 joints	7" 20# K-55 intermediate casing
3372' set at 3383'. Cemented with 280	
held 1200#/30 minutes. Top of cement	at 2700'. Sala 5 9 5 5805
Tiera 1800% to miliacos. Top of comore	
10/23/78: T.D. 7619'. Ran 211 joints	4 1/2", 10.5# K-55 casing liner.
· · · · · · · · · · · · · · · · · · ·	, , , , , , , , , , , , , , , , , , ,

7608' set 7619'. Float collar set at 7611'. Cemented with 653 cu. ft. cement. WOC 18 hours. Top of cement 3000'.

11/9/78: PBTD 7611'. Tested casing to 4000#, OK. Perfed 7343,7352, 7362,7372,7430,7457,7481,7494,7519,7528.7543.7550 with 1 SPZ. 2004.

1304,1314,1430,1431	,/401,/494	F,/313,/340,	/ 3 43, /	/ 330 WIGH I SPA - 5 % 19 %	
Fraced w/153,000# 2	20/40 sand	and 127,000	gal.	water. Flushed w/5000	
gal. water.		·		그는 물건의 원리 내 역 관광호의 기	
Subsurface Safety Valve: Manu. and Type				Set @	Ft.
				សម័ន្ធ ប្រែក្រុម ប្រុស្សា ស្រុក	

18. I hereby certify that the foregoing is true and correct			Ω 2
SIGNED D. F. FALSCO	TITLE Drilling Clerk	nn 11/10/78	
	(This space for Federal or State office use)		
ADDDOVED BY	TITLE ()		

CONDITIONS OF APPROVAL, IF ANY:

NOV 15 1978 OIL CON. COM. DIST. 3

*See Instructions on Reverse Side