STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

May 7, 1984

Mr. Eddie Marcum
El Paso Natural Gas Co.
P.O. Box 990
Farmington, NM 87401

Re: San Juan 28-7 Unit #91 B-24-28N-7W

San Juan 29-7 Unit #44-A I-17-29N-7W

Warren #4 H-14-28N-9W

Dear Eddie:

The enclosed packer tests on the referenced wells were inconclusive in proving zone separation.

Please reschedule and retest the wells in such a manner as to prove separation. Shut both zones in for a minimum of 3 days and blow the higher pressured zone to the atmosphere for as long as it takes to get a significant pressure drop. Please advise this office at least 24 hours prior to the tests so we may provide a witness.

If you have any questions, please contact this office.

Yours Aruly,

Charles Gholson

Deputy Oil & Gas Inspector

CG/dj

cc: Well File