UNITED STATES DEPARTMENT OF THE INTERIOR

18. I hereby certify that the foregoing is true and correct

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 078503-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 29-7 Unit 8. FARM OR LEASE NAME.
1. oil gas X other	San Juan 29-7 Unit 9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	116 10. FIELD OR WILDCAT NAME Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30, T-29-N, R-7-W N.M.P.M. 12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6273' G.L.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	rectionally drilled, give subsurface locations and
9-6-79: Spudded well. Drilled surface hole.	
9-7-79: Ran 5 joints of 9 5/8", 36# KS surface of w/224 cu. ft. cement. Circulated to sur 30 minutes.	SEP 13 1979
Subsurface Safety Valve: Manu. and Type	Set @ST. 3

*See Instructions on Reverse Side

(This space for Federal or State office use)

TITLE _

TITLE ___Drilling Clerk DATE __Sept.

DATE