UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Dec. 1973 UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Form Approved. Budget Bureau No. 42–R1424
	5. LEASE SF 078503A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 29-7 Unit 8. FARM OR LEASE NAME
1. oil gas well to other 2. NAME OF OPERATOR	San Juan 29-7 Unit 9. WELL NO.
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	116 10. FIELD OR WILDCAT NAME Basin Dakota
Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30, T-29-N, R-7-W
	12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6273 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)

14-74-F

well well other 2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space below.) 800'S, 1250'W AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOT REPORT, OR OTHER DATA SUBSEQUENT REPORT OF REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 3-16-80: PBTD 7443'. Tested casing to 4000#, OK. Perfed 7209,7214,7219,7224,7229, 7233,7237,7241,7307,7310,7341,7346,7371,7376,7389' W/1 SPZ. Fraced w/ 125,000 # & 45,000# 20/40 & 10/20 sand, 62,000 gal. wtr. Flushed w/4864 gal. wtr. OIL CON. COM. DIST. 3 Subsurface Safety Valve: Manu. and Type _ 18. I hereby certify that the foregoing is true and correct Drilling Clerk March 17, 1980 (This space for Federal or State office use) APPROVED BY TITLE DATE CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

MAR 2 5 1980

U. S. GEOLOGICAL SURVEY DURANGO, COLO.

MAR 25 '80 DISTRICT DISTRICT

