

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

2. NAME OF OPERATOR  
El Paso Natural Gas Company

3. ADDRESS OF OPERATOR  
P.O. Box 289, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1810'N 1660'W  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

(other) Plug surface hole.

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE

SF 078425

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

San Juan 29-7 Unit

8. FARM OR LEASE NAME

San Juan 29-7 Unit

9. WELL NO.

61A (MD)

10. FIELD OR WILDCAT NAME

Blanco MV & Basin Dakota

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA Sec. 34, T-29-N, R-7-W  
NMPM

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, RDB, AND WD)

6747 GL

RECEIVED  
FEB 27 1981

(NOTE: Report results of multiple completion or zone survey in Form 9-330.)  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

RECEIVED  
MAR 9 1981  
OIL CON. COM.  
DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

2-23-81: Drilled 17 1/2", surface hole to 246'. Ran 5 joints 13 3/8" 48#, H-40 casing 207' set at 223'. Cemented w/ 283 cf. cement. Circulated five barrels slurry to surface. Cement fell back 35'. Attempted to recement. Surface casing had been backed off down hole with top of fish at 46'. Could not screw back into fish. Filled surface hole with 148 cu. ft. cement. Left 13 3/48" casing with 30' cement plug in bottom from 222' to 46'. Left cement plug from 46' to surface. Will skid rig 10' forward and respu.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED A. P. Brisco TITLE Drilling Clerk DATE February 25, 1981

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

ACCEPTED FOR RECORD

MAR 6 1981