Form 9-331 Dec. 1973

Form Approved.	
Budget Bureau No.	42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF 078503
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 29-7 Unit
1. oil gas well other	8. FARM OR LEASE NAME San Juan 29-7 Unit 9. WELL NO. 118 10. FIELD OR WILDCAT NAME
2. NAME OF OPERATOR Paso Natural Gas Company	
3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, NM 87041	Blanco PC Ext. 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 910'S, 1550'E	AREA Sec. 31, T-29-N, R-7-W NMPM
AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is domeasured and true vertical depths for all markers and zones pertiner -20-81: Spudded well. Drilled surface hole. Ran 5 casing 124' set at 137'. Cemented w/ 106 cu WOC 12 hours; held 600#/30 minutes.	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and nt to this work.)* joints 8 5/8", 24#, J-55 surface a. ft. cement. Circulated to surface
	JUL 2 - 1981 OIL CON. COM. DIST. 3
Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct	_
18. I hereby certify that the foregoing is true and correct	erk DATE <u>June 24, 1981</u>

