

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well

GAS

2. Name of Operator

Meridian Oil Inc.

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

910'FSL, 1550'FEL Sec.31, T-29-N, R-7-W, NMPM

5. Lease Number

SF-078503

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

San Juan 29-7 Unit

8. Well Name & Number

San Juan 29-7 U #118

9. API Well No.

30-039-

10. Field and Pool

Blanco PC

11. County and State

Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☒ Notice of Intent☐ Abandonment☐ Change of Plans☐ Subsequent Report☐ Recompletion☐ New Construction☐ Final Abandonment☐ Plugging Back☐ Non-Routine Fracturing☐ Casing Repair☐ Water Shut off☐ Altering Casing☐ Conversion to Injection☐ Other -

13. Describe Proposed or Completed Operations

Production for this Pictured Cliffs well has been evaluated by isolating a casing failure with a packer and tubing. It was determined that this well is incapable of adequate production to merit a casing repair. A plug and abandonment procedure will be submitted in the near future with work planned to be completed by November 1993.

070 FARMINGTON, NM

93 FEB 12 PM 2:51

RECEIVED
BLM

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] (KS) Title Regulatory Affairs Date 2/12/93

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

WMOO

FARMINGTON RESIDENT
BY [Signature]