

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-10037-46	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER- <input type="checkbox"/>	7. Unit Agreement Name San Juan 29-7 Unit
Name of Operator El Paso Natural Gas Company			8. Farm or Lease Name San Juan 29-7 Unit
Address of Operator PO Box 4289, Farmington, NM 87499			9. Well No. 31E
Location of Well UNIT LETTER <u>A</u> <u>800</u> FEET FROM THE <u>North</u> LINE AND <u>910</u> FEET FROM <u>East</u> <u>32</u> <u>29N</u> <u>7W</u> THE <u>LINE, SECTION</u> <u>TOWNSHIP</u> <u>RANGE</u> <u>NMPM.</u>			10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 6563' GL			12. County Rio Arriba

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <u>Frac Report</u> <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-24-85

PBTD 7763'. Tested casing to 4000#, ok. Perforated 7554', 7558', 7562', 7565', 7571', 7574', 7578', 7581', 7584', 7587', 7590', 7593', 7596', 7654', 7683', 7686', 7690', 7722', 7753', 7759' with 1 spz. Fraced with 138,000# 20/40 sand and 108,780 gallons treated water. Flushed with 4950 gallons water. Top of cement on 4 1/2" casing at 3400' by cement bond log.

RECEIVED
MAR 11 1985
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Drilling Clerk</u>	DATE <u>March 8, 1985</u>
---------------------------	-----------------------------	---------------------------

APPROVED BY <u>Original Signed by FRANK T. CHAVEZ</u>	TITLE <u>SUPERVISOR DISTRICT # 3</u>	DATE <u>MAR 11 1985</u>
---	--------------------------------------	-------------------------

CONDITIONS OF APPROVAL, IF ANY: