UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Not	ices and Reports on Wel	.ls. v.0	
1. Type of We	11	1.9 m m	5.	SF-078424 If Indian, All. or Tribe Name
2. Name of Op BURL RESO	INGTON	& GAS COMPANY	ECEIVE NOV - 5 1938.	Unit Agreement Name Jan Juan 29-7 Unit Well Name & Number
4. Location o	f Well, Footage, S	87499 (505) 326-97 08/1	- DIM. 3 10.	San Juan 29-7 U #45A YAPI Well No. 030-039-23955 Field and Pool Blanco MV/Basin DK County and State Rio Arriba Co, NM
Type of Su NoX_ Su		Type of Ac Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other - Commingle	Change of Pl Change of Pl New Construct Non-Routine Water Shut of Conversion to	ans ction Fracturing off
13. Describ 10-8-98 10-9-98 10-12-9 10-13-9 10-14-9 10-15-9 10-16-9	Blow well & CO. SD for weekend TIH w/mill, tag TOOH. TIH to TIH, tag up @ 8 Blow well & CO. TIH, tag CIBP @ EUE tbg, land	BOP. TIH, tag up @ 623 TOOH w/1 ½" Dakota tbg d. top of Model "D" pkr.	Establish circ. PBTD @ 8123'. @ 7980'. TOOH. TOOH. TIH w/24	seal assembly. TOOH. Mill out Model "D" pkr Circ hole clean. SDON. SDON. 14 jts 2 3/8" 4.7# J-55
		saverde/Dakota commingl		59.
Signed Man	y certify that the		lministrator_Dat	ACCEPTED FOR RECORD
APPROVED BY _	APPROVAL, if any:	Title	Date _	OCT 2 7 1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to proceed a TAICH OFFICE or agency of the United States any false, fictitious or fraudulent statements or representations and the matter within its jurisdiction.