## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

DEPARTMENT OF THE INTERIOR	ស្រាស់ សេជាស	
BUREAU OF LAND MANAGEMENT	5, 115 11 2011	
Sundry Notices and Reports on	Wells	· · · · · · · · · · · · · · · · · · ·
Sundry Notices and Neptro In	3 113 15 PH 2: 56	<u> </u>
	5.	Lease Number
	enal Pi 🔉	SF-078423  If Indian, All. or
1. Type of Well		Tribe Name
GAS		TIESE Name
	7.	Unit Agreement Name
2. Name of Operator		
MERIDIAN OIL		San Juan 29-7 Unit
	8.	Well Name & Number
3. Address & Phone No. of Operator		San Juan 29-7 U #57A
PO Box 4289, Farmington, NM 87499 (505) 326-9	700 9.	
		30-039- . Field and Pool
4. Location of Well, Footage, Sec., T, R, M		Blanco MV/Basin DK
1850'FNL, 1840'FWL, Sec.11, T-29-N, R-7-W, NMPM	1 11	. County and State
		Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NO	TICE, REPORT, OTHE	R DATA
Type of Submission Type of	of Action X Change of F	
X Notice of Intent Abandonment Recompletion	_ <del>_</del>	ction
Subsequent Report Plugging Back		Fracturing
Casing Repair	Water Shut	
	ing Conversion	to Injection
Other -		
13. Describe Proposed or Completed Operations		
It is intended to change the cement on the	9 5/8" intermediate	e casing as follows:
Single stage: Cement to circulate to		
/o are mag Florolo 5 ppg Gilsonite	. Tail with 190 sa	CKS Class B 30/30 poz
Litt 20 Laium ablaride 0 25 pps F	locele (1991 cu.it	. Of Stuffy, ooe excess co
circulate to surface). Wait on cemen	t 12 hours prior t	o drilling out intermediate
casing. Test casing to 1500 psi for	30 minutes.	
		The Maria
		MEGRATA
		28 MAR 2 0 1898 :
		, iiii 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
		QM strain to a
		in the state of th
14. I hereby certify that the foregoing is true	and correct.	
Signed May Manhaeld (DTV7) Title Reg	ulatory Administra	tor Date 3/14/96
7444		
(This space for Federal or State Office use)		
APPROVED BYTitle	Date	
CONDITION OF APPROVAL, if any:		

APPROVED

MAR 1 8 1996

For DISTRICT MANAGED