UNITED STATES

DEPARTMENT OF THE ENTERIOR BUREAU OF LAND MANAGEMENT

	the management process of the confidence of the		
Sundry Not	tices and Reports on Wells		
1. Type of Well GAS	DEGETVE	5. 6.	SF-078399
	OIL COM. DI	y7. 7.	Unit Agreement Name
2. Name of Operator BURLINGTON	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)		
3. Address & Phone No. of Opera		8.	San Juan 29-7 U #66
PO Box 4289, Farmington, N	M 87499 (505) 326-9700	9.	API Well No. 30-039-25664
4. Location of Well, Footage, 5 2040'FNL, 2175'FWL, Sec. 22,			Field and Pool Blanco MV/Basin DK
NSL-3778 DHC-1589		11.	County and State Rio Arriba Co, NM
Final Abandonment 13. Describe Proposed or Comp 8-7-97 MIRU. ND WH. NU B	Casing Repair Wat Altering Casing ConX_ Other - Commingle pleted Operations BOP. TOOH w/195 jts 2 3/8" tbg	version to	o Injection
	? @ 6050'. Blow well & CO to 3/8" 4/7# J-55 EUE tbg, landed		ND BOP. NU WH. RD.
			RECEIVED AND 12 PH 12: 54 THIS 12 PH 12: 54
14. I hereby certify that the	Fitle Regulatory Administ		8/11/97
(This space for Federal or State	Title <u>Requlatory Administ</u>		
APPROVED BY	Title	Da ACCE	PTED FOR RECORD
CONDITION OF APPROVAL, if any:	N.		AUG 1 8 1997

FARMINGTON DISTRICT OFFICE
BY