## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notic	ces and Reports on Wells
1. Type of Well GAS  2. Name of Operator	5. Lease Number  SF-078423 6. If Indian, All. or  Tribe Name  Unit Agreement Name  San Juan 29-7 Unit
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM  4. Location of Well, Footage, Sec. 785' FNL, 400' FWL, Sec. 14,	87499 (505) 326-9700 9. API Well No. 30-039- 25858 c., T, R, M 10. Field and Pool
Type of Submission  _X Notice of Intent  Subsequent Report  Final Abandonment	Type of Action  Abandonment X Change of Plans Recompletion New Construction Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection X Other
following manner:  First stage - Set s  neat cmt w/3% Ed  Tail w/90 sx Cla  pps Flocele, 7 m	eted Operations  The composition of the subject well in the stage tool @ 2544'. Lead cmt 7" csg w/47 sx Class "B" conolite, .50 pps Flocele, 7 pps Gilsonite (136 cu ft).  The composition of the subject well in the stage tool @ 2544'. Lead cmt 7" csg w/47 sx Class "B" conolite, .50 pps Gilsonite (136 cu ft).  The composition of the subject well in the stage tool well as "B" conolite, .50 pps Gilsonite (136 cu ft).  The composition of the subject well in the stage well in the stage tool well as "B" conolite, .50 pps Gilsonite (136 cu ft).  The composition of the subject well in the stage well in the stage tool @ 2544'. Lead cmt 7" csg w/47 sx Class "B" conolite, .50 pps Gilsonite (136 cu ft).  The composition of the subject well in the stage well in the stage well as the composition of the composition
14. 2 hereby certify that the	foregoing is true and correct.  Title Regulatory Administrator Date 7/15/98
(This space for Spenderal WrSpenderal APPROVED BY CONDITION OF APPROVAL, if any:	(VKI)