

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

July 9, 2002

Dolores Silseth Burlington Res O&G Co PO Box 4289 Farmington NM 87499

Re: San Juan 29-7 Unit 56, A-15-29N-07W, API# 30-039-60102

Dear Dolores:

The Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before September 15, 2002.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin

Deputy Oil & Gas Inspector

Charlie T. L. rrin

cperrin@state.nm.us

CTP/mk

CC: CTP

Well File