

The following data was obtained during a packer leakage test performed on the Dalhi-Taylor Frichard #4 K SW 31-29N-8W

Upper Completion - Pictured Cliffs
Lower Completion - Blanco-Masverde

Date of Test - July 23, 1956

Packer Set at 2275'

Lower Zone Tubing String - 0' - 2283' 2 1/2" 6.50#
2283' - 4522' 2" 4.70#

Casing Sizes and Depth - 7" 20# 0-2347'
4 1/2" 9.50# 2295' - 4605'

Perforations: 2208' - 2256'
3898' - 3940'
4450' - 4546'

During Test, Csg. was open Tbg. was shut-in.

Time	Csg. Pres. Psig	Tbg. Pres. Psig	Flow Temp Deg. F	Vol. MCF/day
10:20 A.M.	939	1004	-	-
10:27 A.M.	Opened	1004	-	-
11:27 A.M.	-	1004	60° (Est.)	3,823
12:05 P.M.	-	1004	60° (Est.)	2,963
12:45 P.M.	-	1005	63° (Est.)	2,676
1:15 P.M.	-	1005	65° (Est.)	2,580

Tested by: J. E. Kruger
Dist. Engineer

Witnessed by: Wm. M. L. Johnson
Asst. Field Supt.

Witnessed by: F. H. Cook
New Mexico Oil Conservation Commission

cc: J. B. Howell
W. C. Smith
H. P. Kerr
R. G. Carlin



The following data was obtained from a recent test performed at the Department of Defense, July 1952:

Test results - 100% correct
 Test results - 100% correct

Date of test - July 1952

Location of test - 100%

Test results - 100% correct
 Test results - 100% correct

Test results - 100% correct
 Test results - 100% correct

Test results - 100% correct
 Test results - 100% correct

Test results - 100% correct
 Test results - 100% correct

Test results	Test results	Test results	Test results	Test results
100%	100%	100%	100%	100%
100%	100%	100%	100%	100%
100%	100%	100%	100%	100%
100%	100%	100%	100%	100%
100%	100%	100%	100%	100%
100%	100%	100%	100%	100%
100%	100%	100%	100%	100%
100%	100%	100%	100%	100%
100%	100%	100%	100%	100%

Test results - 100% correct
 Test results - 100% correct
 Test results - 100% correct
 Test results - 100% correct

Test results - 100% correct
 Test results - 100% correct
 Test results - 100% correct
 Test results - 100% correct

