



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval No. 42-61-00.
Land Office OTC046
Lease No. M. V. Strat Test
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 26

57

Well No. 3 is located 1600 ft. from XX line and 1460 ft. from XX line of sec. 21
Blanco San Juan New Mexico
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian) (State or Territory)
(Field) (County or Subdivision) 8474

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(On 12-22-57) Ran 101 joints 7 5/8", J-55, 26.40#, casing 3265' set at 3275' with 100 sacks regular cement, 100 sacks Foxmix, 50# Flocale and 4# Gel, followed with 50 sacks Neat cement. Held 1000# 30 minutes.

Top of cement by temperature survey at 2780'.



I understand that this plan of operations has been approved by the Geological Survey before operations may be commenced.

Company Box 997
Address Farmington, New Mexico
Original Signed D. C. Johnston
By Petroleum Engineer
Title _____