

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078415
Unit H. E. Roelofs

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Jan. 12, 1951

Well No. 1 is located 990 ft. from [N] line and 2310 ft. from [E] line of sec. 22
SW/4 SE/4 NE/4 Sec. 22 29N 8W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat San Juan N. Mex.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6678.5 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 5796'
Gauged 100 MCF Natural before shot
Shot 900 qts. liquid Nitro-Glycerin from 5946-5796
Cleaned out to 5676
Ran 2 3/8" O. D. 4.70# Tubing to 5721 feet
Gauged 5,800 MCF after shot
Shut in Press. 877 after 24 hrs.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Byrd-Frost, Inc.

Address Box 911

Durango, Colo.

By John Carothers

Title Dist. Office Mgr.