

District I

P.O. Box 1980, Hobbs, NM

District II

P.O. Drawer DD, Artesia, NM 88211

District III

Rio Brazos Rd., Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088SUBMIT 1 COPY TO  
APPROPRIATE  
DISTRICT OFFICE  
AND 1 COPY TO  
SANTA FE OFFICEPIT REMEDIATION AND CLOSURE REPORT

Operator: Amoco Production Company Telephone: (505) 326-9200

Address: 200 Amoco Court, Farmington, New Mexico 87401

Facility Or: FLORANCE #30  
Well Name

Location: Unit or Qtr/Qtr Sec M Sec 1 T 29N R 8W County SAN JUAN

Pit Type: Separator Dehydrator Other ABANDONED ROW

Land Type: BLM ☒, State ☐, Fee ☐, Other ☐Pit Location: Pit dimensions: length NA, width NA, depth NA  
(Attach diagram)Reference: wellhead ☒, other ☐

Footage from reference: 132'

Direction from reference: 10 Degrees East North ☒  
of  
☒ West South ☐

## Depth To Ground Water:

(Vertical distance from  
contaminants to seasonal  
high water elevation of  
ground water)Less than 50 feet (20 points)  
50 feet to 99 feet (10 points)  
Greater than 100 feet (0 Points)

0

## Wellhead Protection Area:

(Less than 200 feet from a private  
domestic water source, or; less than  
1000 feet from all other water sources)Yes (20 points)  
No (0 points)

0

## Distance To Surface Water:

(Horizontal distance to perennial  
lakes, ponds, rivers, streams, creeks,  
irrigation canals and ditches)Less than 200 feet (20 points)  
200 feet to 1000 feet (10 points)  
Greater than 1000 feet (0 points)

0

RANKING SCORE (TOTAL POINTS):

0

Date Remediation Started: \_\_\_\_\_ Date Completed: 9/9/00

Remediation Method: Excavation ☒ Approx. cubic yards NA  
(Check all appropriate sections) Landfarmed \_\_\_\_\_ Insitu Bioremediation \_\_\_\_\_  
Other CLOSE AS IS

Remediation Location: Onsite ☒ Offsite \_\_\_\_\_  
(ie. landfarmed onsite, name and location of offsite facility)

General Description Of Remedial Action: \_\_\_\_\_  
Excavation . NO REMEDIATION NECESSARY.

Ground Water Encountered: No ☒ Yes \_\_\_\_\_ Depth \_\_\_\_\_

Final Pit: Sample location see Attached Documents

Closure Sampling: \_\_\_\_\_  
(if multiple samples, attach sample results and diagram of sample locations and depths)

Sample depth 12' (TEST HOLE BOTTOM)

Sample date 9/1/00 Sample time 1050

## Sample Results

Benzene (ppm) \_\_\_\_\_

Total BTEX (ppm) \_\_\_\_\_

Field headspace (ppm) 0.0

TPH ND ppm

Ground Water Sample: Yes \_\_\_\_\_ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 9/9/00

SIGNATURE

B. Shaw

PRINTED NAME  
AND TITLE

Buddy D. Shaw  
Environmental Coordinator

3004508638

CLIENT: AMOCOBLAGG ENGINEERING, INC.  
P.O. BOX 87, BLOOMFIELD, NM 87413  
(505) 632-1199LOCATION NO: 80788C.D.C. NO: 8/65

## FIELD REPORT: CLOSURE VERIFICATION

PAGE NO: 1 of 1LOCATION: NAME: FLORANCEWELL #: 30 PIT: ABD. FLAREQUAD/UNIT M SEC: 1 TWP: 29N RNG: 8W PM: NM CNTY: SJ ST: NMDATE STARTED: 8-28-00DATE FINISHED: 9-1-00QTR/FOOTAGE: SW/4 SW/4 <sup>870' 5'</sup> <sub>830' 5'</sub> CONTRACTOR: FLINTENVIRONMENTAL SPECIALIST: BLAGG

~~PIT~~  
EXCAVATION APPROX. 45' FT. x 30' FT. x 8' FT. DEEP. CUBIC YARDAGE: 0  
DISPOSAL FACILITY: N/A <sup>ON-SITE</sup> REMEDIATION METHOD: N/A <sup>CLOSE AS IS</sup>  
LAND USE: RANGE LEASE: SF 078596-A FORMATION: OK/MU

## FIELD NOTES &amp; REMARKS:

PIT LOCATED APPROXIMATELY 132 FT. N10°W FROM WELLHEADDEPTH TO GROUNDWATER: >100 NEAREST WATER SOURCE: >1000 NEAREST SURFACE WATER: >1000NMDCD RANKING SCORE: 0 NMDCD TPH CLOSURE STD: 5000 PPM

## CHECK ONE

## SOIL AND EXCAVATION

OVM CALIB. READ. 51.2 ppm☒ PIT ABANDONED☐ STEEL TANK INSTALLED☐ FIBERGLASS TANK INSTALLED

## DESCRIPTION:

TIME: 1755 (am) pm

PIT LOCATED IN SAND/SILT CLAY MIX, yellow orange, moist, Non Cohesive.  
No HC ODOR or staining in PIT. Thin layer, 2", of Cement on PIT Surface.

Test hole dug to 4' Below PIT Base w/ Backhoe. - SAME LITHOLOGY,  
No HC ODOR or staining.

CLOSED

## FIELD 418.1 CALCULATIONS


| TIME | SAMPLE I.D. | LAB No: | WEIGHT (g) | mL. FREON | DILUTION | READING | CALC. ppm |
|------|-------------|---------|------------|-----------|----------|---------|-----------|
|      |             |         |            |           |          |         |           |
|      |             |         |            |           |          |         |           |
|      |             |         |            |           |          |         |           |
|      |             |         |            |           |          |         |           |

SCALE



0 FT

## PIT PERIMETER



## OVM RESULTS


| SAMPLE ID | FIELD HEADSPACE PID (ppm) |
|-----------|---------------------------|
| 1 @ 12'   | 0.0                       |
| 2 @       |                           |
| 3 @       |                           |
| 4 @       |                           |
| 5 @       |                           |

## LAB SAMPLES

| SAMPLE ID | ANALYSIS | TIME  |
|-----------|----------|-------|
| LC12'     | TPH BUI5 | 10:50 |
|           |          |       |
|           |          |       |
|           |          |       |
|           |          |       |

CLOSED

## PIT PROFILE



## TRAVEL NOTES:

CALLOUT: \_\_\_\_\_

ONSITE: \_\_\_\_\_



District I

P.O. Box 1980, Hobbs, NM

District II

P.O. Drawer DD, Artesia, NM 88211

District III

Rio Brazos Rd, Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO  
APPROPRIATE  
DISTRICT OFFICE  
AND 1 COPY TO  
SANTA FE OFFICE

PIT REMEDIATION AND CLOSURE REPORTOperator: Amoco Production Company Telephone: (505) - 326-9200Address: 200 Amoco Court, Farmington, New Mexico 87401Facility Or: FLOORPCE #30  
Well NameLocation: Unit or Qtr/Qtr Sec M Sec 1 T29N R8W County SAN JUANPit Type: Separator    Dehydrator    Other ABANDONED PRODUCTION TANKLand Type: BLM ✓, State   , Fee   , Other   Pit Location: Pit dimensions: length NA, width NA, depth NA  
Attach diagram)Reference: wellhead X, other   Footage from reference: 110'Direction from reference: 12 Degrees ✓ East North     
of  
   West South ✓

## Depth To Ground Water:

(Vertical distance from  
contaminants to seasonal  
high water elevation of  
ground water)

Less than 50 feet (20 points)  
50 feet to 99 feet (10 points)  
Greater than 100 feet (0 Points) 0

## Wellhead Protection Area:

(Less than 200 feet from a private  
domestic water source, or; less than  
1000 feet from all other water sources)

Yes (20 points)  
No (0 points) 0

## Distance To Surface Water:

(Horizontal distance to perennial  
lakes, ponds, rivers, streams, creeks,  
irrigation canals and ditches)

Less than 200 feet (20 points)  
200 feet to 1000 feet (10 points)  
Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS):

0

Date Remediation Started: \_\_\_\_\_ Date Completed: 9/9/00Remediation Method: Excavation ☒ Approx. cubic yards NA  
(Check all appropriate sections) Landfarmed ☐ Insitu Bioremediation ☐  
Other CLOSE AS IS.Remediation Location: Onsite ☒ Offsite \_\_\_\_\_  
(ie. landfarmed onsite, name and location of offsite facility)General Description Of Remedial Action: \_\_\_\_\_  
Excavation . BEDROCK BOTTOM, NO REMEDIATION NECESSARY.Ground Water Encountered: No ☒ Yes ☐ Depth \_\_\_\_\_Final Pit: \_\_\_\_\_ Sample location see Attached DocumentsClosure Sampling: \_\_\_\_\_  
(if multiple samples, attach sample results and diagram of sample locations and depths) Sample depth 6' (TEST HOLE BOTTOM)Sample date 9/1/00 Sample time 1115

## Sample Results:

Benzene(ppm) \_\_\_\_\_

Total BTEX(ppm) \_\_\_\_\_

Field headspace(ppm) 0.0TPH NED ppmGround Water Sample: Yes ☐ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 9/9/00

SIGNATURE

B. ShawPRINTED NAME  
AND TITLEBuddy D. Shaw  
ENVIRONMENTAL COORDINATOR

CLIENT: AMOCOBLAGG ENGINEERING, INC.  
P.O. BOX 87, BLOOMFIELD, NM 87413  
(505) 632-1199LOCATION NO: 80788C.D.C. NO: 8165

## FIELD REPORT: CLOSURE VERIFICATION

PAGE No: 1 of 1LOCATION: NAME: FLORANCE WELL #: 30 PIT: ABD. TANK.QUAD/UNIT: M SEC: 1 TWP: 29N RNG: 8W PM: NM CNTY ST: NMQTR/FOOTAGE: SW 1/4 SW 1/4 CONTRACTOR: FLINTDATE STARTED 8-28-00DATE FINISHED 9-1-00ENVIRONMENTAL SPECIALIST: BLAGGPIT EXCAVATION APPROX. 12 FT. x 10 FT. x 3 FT. DEEP. CUBIC YARDAGE 0  
DISPOSAL FACILITY: ATA ON-SITE REMEDIATION METHOD: ATA CLOSE AS IS  
LAND USE: RANGE LEASE: SF 078596 A FORMATION: OR/MVFIELD NOTES & REMARKS: PIT LOCATED APPROXIMATELY 110 FT. S 12° E FROM WELL-HEAD  
DEPTH TO GROUNDWATER: >100 NEAREST WATER SOURCE: >1000 NEAREST SURFACE WATER: >1000NMOC RANKING SCORE: 0 NMOC TPH CLOSURE STD: 5000 PPM

SOIL AND EXCAVATION

DESCRIPTION:

DVM CALIB. READ. 51.2 ppm  
TIME: 0755 am/pm

CHECK ONE

☒ PIT ABANDONED☐ STEEL TANK INSTALLED☐ FIBERGLASS TANK INSTALLEDPIT LOCATED IN SAND/SILT/CLAY MIX, yellow orange, Dry, Non Cohesive.  
No HC ODOOR OR STAIN.DUG Test Pit with Backhoe in Base of Pit. Found Shalestone  
Bedrock @ 2' Below Pit Bottom. No HC ODOOR OR STAIN  
in Test hole.BEDROCK  
BOTTOM

CLOSED

## FIELD 418.1 CALCULATIONS


| TIME | SAMPLE I.D. | LAB No: | WEIGHT (g) | mL. FREON | DILUTION | READING | CALC. ppm |
|------|-------------|---------|------------|-----------|----------|---------|-----------|
|      |             |         |            |           |          |         |           |
|      |             |         |            |           |          |         |           |
|      |             |         |            |           |          |         |           |

SCALE



0 FT

PIT PERIMETER


OVM  
RESULTS

| SAMPLE<br>ID | FIELD HEADSPACE<br>PID (ppm) |
|--------------|------------------------------|
| 1 e          | 0.0                          |
| 2 e          |                              |
| 3 e          |                              |
| 4 e          |                              |
| 5 e          |                              |

## LAB SAMPLES

| SAMPLE<br>ID | ANALYSIS | TIME |
|--------------|----------|------|
| C106         | TPH 8/5  | 1115 |
|              | PASSED   |      |


## PIT PROFILE



TRAVEL NOTES:

CALLOUT:

ONSITE:



2709-D Pan American Freeway NE  
Albuquerque, New Mexico 87107  
Phone (505) 344-3777  
Fax (505) 344-4413

### GAS CHROMATOGRAPHY RESULTS

TEST : EPA 8015 MODIFIED (DIRECT INJECT)  
CLIENT : ENVIROTECH, INC.  
PROJECT # : 403410  
PROJECT NAME : BLAGG/BP-AMOCO

PINNACLE I.D.: 009035

| SAMPLE                     |               |            | DATE     | DATE          | DATE         | DIL.         |
|----------------------------|---------------|------------|----------|---------------|--------------|--------------|
| ID. #                      | CLIENT I.D.   | MATRIX     | SAMPLED  | EXTRACTED     | ANALYZED     | FACTOR       |
| 01                         | C @ 12'/18072 | NON-AQ     | 09/01/00 | 09/07/00      | 09/09/00     | 1            |
| 02                         | C @ 6'/18073  | NON-AQ     | 09/01/00 | 09/07/00      | 09/09/00     | 1            |
| 03                         | C @ 8'/18074  | NON-AQ     | 09/01/00 | 09/07/00      | 09/09/00     | 1            |
| PARAMETER                  |               | DET. LIMIT | UNITS    | C @ 12'/18072 | C @ 6'/18073 | C @ 8'/18074 |
| FUEL HYDROCARBONS, C6-C10  |               | 10         | MG/KG    | < 10          | < 10         | 230          |
| FUEL HYDROCARBONS, C10-C22 |               | 10         | MG/KG    | < 10          | < 10         | 86           |
| FUEL HYDROCARBONS, C22-C36 |               | 10         | MG/KG    | < 10          | < 10         | 35           |
| CALCULATED SUM:            |               |            |          |               |              | 351          |

#### SURROGATE:

D-TERPHENYL (%)

SURROGATE LIMITS

( 66 - 151 )

107

108

101

#### CHEMIST NOTES:

N/A

District I  
P.O. Box 1980, Hobbs, NM  
District II  
P.O. Drawer DD, Artesia, NM 88211  
District III  
J Rio Brazos Rd, Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO  
APPROPRIATE  
DISTRICT OFFICE  
AND 1 COPY TO  
SANTA FE OFFICE

## PIT REMEDIATION AND CLOSURE REPORT

Operator: Amoco Production Company Telephone: (505) 326-9200  
Address: 200 Amoco Court, Farmington, New Mexico 87401  
Facility Or: FLORANCE #30  
Well Name \_\_\_\_\_  
Location: Unit or Qtr/Qtr Sec M Sec 1 T 29N R 8W County SAN JUAN  
Pit Type: <sup>ABANDONED</sup> Separator ☒ Dehydrator ☐ Other ☐  
Land Type: BLM ☒ State ☐ Fee ☐ Other ☐

Pit Location: Pit dimensions: length 25', width 20', depth 11'  
(Attach diagram)  
Reference: wellhead ☒, other ☐  
Footage from reference: 95'  
Direction from reference: 57 Degrees ☒ East North ☐  
West South ☒

Depth To Ground Water:  
(Vertical distance from  
contaminants to seasonal  
high water elevation of  
ground water)

|                       |                     |
|-----------------------|---------------------|
| Less than 50 feet     | (20 points)         |
| 50 feet to 99 feet    | (10 points)         |
| Greater than 100 feet | (0 Points) <u>0</u> |

Wellhead Protection Area:  
(Less than 200 feet from a private  
domestic water source, or; less than  
1000 feet from all other water sources)

|     |                     |
|-----|---------------------|
| Yes | (20 points)         |
| No  | (0 points) <u>0</u> |

Distance To Surface Water:  
(Horizontal distance to perennial  
lakes, ponds, rivers, streams, creeks,  
irrigation canals and ditches)

|                        |                     |
|------------------------|---------------------|
| Less than 200 feet     | (20 points)         |
| 200 feet to 1000 feet  | (10 points)         |
| Greater than 1000 feet | (0 points) <u>0</u> |

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: \_\_\_\_\_ Date Completed: 9/9/00Remediation Method: Excavation ☒ Approx. cubic yards 175  
(Check all appropriate sections) Landfarmed ☐ Insitu Bioremediation ☐  
Other COMPOSTEDRemediation Location: Onsite ☐ Offsite NYE GC B#1E (E-7-29-9)  
(ie. landfarmed onsite, name and location of offsite facility) TRANSPORTED TO CRUNCH MESA 3/01. NVGeneral Description Of Remedial Action: \_\_\_\_\_  
Excavation. BEDROCK BOTTOM.Ground Water Encountered: No ☒ Yes ☐ Depth \_\_\_\_\_Final Pit: Sample location see Attached Documents  
Closure Sampling: \_\_\_\_\_  
(if multiple samples, attach sample results and diagram of sample locations and depths) Sample depth 8' (SOUTH SIDEWALK)  
Sample date 9/1/00 Sample time 1/45

## Sample Results

Benzene(ppm) ND  
Total BTEX(ppm) 2.5  
Field headspace(ppm) 255  
TPH 351 ppmGround Water Sample: Yes ☐ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 9/9/00

SIGNATURE

B. ShawPRINTED NAME  
AND TITLEBuddy D. Shaw  
Environmental Coordinator

CLIENT: AMOCOBLAGG ENGINEERING, INC.  
P.O. BOX 87, BLOOMFIELD, NM 87413  
(505) 632-1199LOCATION NO: 80788C.D.C. NO: 8165

## FIELD REPORT: CLOSURE VERIFICATION

PAGE No: 1 of 1LOCATION: NAME: FLORANCE WELL #: 30 PIT: ABD SEP  
QUAD/UNIT: M SEC: 1 TWP: 29N RNG: 8W PM: NM CNTY: SJ ST: NM  
QTR/FOOTAGE: SW/4 SW/4 CONTRACTOR: FLINTDATE STARTED: 8-28-00  
DATE FINISHED: 9-1-00ENVIRONMENTAL  
SPECIALIST: BLAGGEXCAVATION APPROX. 25 FT. x 20 FT. x 11 FT. DEEP. CUBIC YARDAGE: 175  
DISPOSAL FACILITY: NYE GC B/E (E7-79-9) REMEDIATION METHOD: LF/COMPOST  
LAND USE: RANGE LEASE: SF 07596A FORMATION: OR/LNVFIELD NOTES & REMARKS: PIT LOCATED APPROXIMATELY 95 FT. S57°E FROM WELL HEAD  
DEPTH TO GROUNDWATER: >100 NEAREST WATER SOURCE: >1000 NEAREST SURFACE WATER: >1000NMCD RANKING SCORE: 0 NMCD TPH CLOSURE STD: 5000 PPM

## SOIL AND EXCAVATION

## DESCRIPTION:

OVM CALIB. READ: 51.2 ppm  
TIME: 0755 am/pm

## CHECK ONE

- ☒
- PIT ABANDONED
- 
- ☐
- STEEL TANK INSTALLED
- 
- ☐
- FIBERGLASS TANK INSTALLED

SAND/SILT/CLAY MIX FROM 0'-8'. ORANGE-YELLOW, Dry to moist, cohesive.  
NO HC ODOR OR STAIN 0'-7'. MINOR STAIN FROM 8'-9'.  
FROM 9'-11', Shalestone Bedrock, MINOR HC ODOR & STAIN.

BEDROCK  
BOTTOM

CLOSED


## FIELD 418.J CALCULATIONS

| TIME | SAMPLE I.D. | LAB No: | WEIGHT (g) | ML. FREON | DILUTION | READING | CALC. ppm |
|------|-------------|---------|------------|-----------|----------|---------|-----------|
|      |             |         |            |           |          |         |           |
|      |             |         |            |           |          |         |           |
|      |             |         |            |           |          |         |           |

SCALE

0 FT

## PIT PERIMETER


OVM  
RESULTS

| SAMPLE I.D. | FIELD HEADSPACE PID (ppm) |
|-------------|---------------------------|
| 1 @ 8'      | 104                       |
| 2 @ 9'      | 255                       |
| 3 @ 10'     | 177                       |
| 4 @ 11'     | 28                        |
| 5 @ 11'     | 169                       |

## LAB SAMPLES

| SAMPLE ID | ANALYSIS | TIME |
|-----------|----------|------|
| 2502      | TPH/BA   | 1145 |
|           |          |      |
|           |          |      |
|           |          |      |

## PIT PROFILE



TRAVEL NOTES:

CALLOUT: \_\_\_\_\_

ONSITE: \_\_\_\_\_



2709-D Pan American Freeway NE  
Albuquerque, New Mexico 87107  
Phone (505) 344-3777  
Fax (505) 344-4413


# GAS CHROMATOGRAPHY RESULTS

TEST : EPA 8015 MODIFIED (DIRECT INJECT)  
CLIENT : ENVIROTECH, INC.  
PROJECT # : 403410  
PROJECT NAME : BLAGG/BP-AMOCO

PINNACLE I.D.: 009035

| SAMPLE                     |              |        |                 |                   |                  |                |
|----------------------------|--------------|--------|-----------------|-------------------|------------------|----------------|
| D. #                       | CLIENT I.D.  | MATRIX | DATE<br>SAMPLED | DATE<br>EXTRACTED | DATE<br>ANALYZED | DIL.<br>FACTOR |
| 01                         | C @ 12/18072 | NON-AQ | 09/01/00        | 09/07/00          | 09/09/00         | 1              |
| 02                         | C @ 6/18073  | NON-AQ | 09/01/00        | 09/07/00          | 09/09/00         | 1              |
| 03                         | C @ 8/18074  | NON-AQ | 09/01/00        | 09/07/00          | 09/09/00         | 1              |
| PARAMETER                  |              |        |                 |                   |                  |                |
|                            | DET. LIMIT   | UNITS  | C @ 12/18072    | C @ 6/18073       | C @ 8/18074      |                |
| FUEL HYDROCARBONS, C6-C10  | 10           | MG/KG  | < 10            | < 10              | 230              |                |
| FUEL HYDROCARBONS, C10-C22 | 10           | MG/KG  | < 10            | < 10              | 86               |                |
| FUEL HYDROCARBONS, C22-C36 | 10           | MG/KG  | < 10            | < 10              | 35               |                |
| CALCULATED SUM:            |              |        |                 |                   | 351              |                |
| SURROGATE:                 |              |        |                 |                   |                  |                |
| p-TERPHENYL (%)            |              |        | 107             | 108               | 101              |                |
| SURROGATE LIMITS           | ( 66 - 151 ) |        |                 |                   |                  |                |

ANALYST NOTES:  
/A



2709-D Pan American Freeway NE  
Albuquerque, New Mexico 87107  
Phone (505) 344-3777  
Fax (505) 344-4413

### GAS CHROMATOGRAPHY RESULTS

TEST : EPA 8021 MODIFIED  
CLIENT : ENVIROTECH, INC.  
PROJECT # : 403410  
PROJECT NAME : BLAGG/BP-AMOCO

PINNACLE I.D.: 009035

| SAMPLE        |             | DATE       |          | DATE      |                      | DATE     |  | DIL.   |  |
|---------------|-------------|------------|----------|-----------|----------------------|----------|--|--------|--|
| D. #          | CLIENT I.D. | MATRIX     | SAMPLED  | EXTRACTED |                      | ANALYZED |  | FACTOR |  |
| 3             | C @ 8/18074 | NON-AQ     | 09/01/00 | 09/07/00  |                      | 09/11/00 |  | 1      |  |
| PARAMETER     |             | DET. LIMIT | UNITS    |           | C @ 8/18074          |          |  |        |  |
| BENZENE       |             | 0.025      | MG/KG    |           | < 0.025 ND <i>AV</i> |          |  |        |  |
| TOLUENE       |             | 0.025      | MG/KG    |           | 0.32                 |          |  |        |  |
| ETHYLBENZENE  |             | 0.025      | MG/KG    |           | 0.18                 |          |  |        |  |
| TOTAL XYLENES |             | 0.025      | MG/KG    |           | 2.0                  |          |  |        |  |

SURROGATE:  
BROMOFLUOROBENZENE (%) 171\*  
SURROGATE LIMITS ( 65 - 120 )

TOTAL BTEX 2.5 ppm *AV*

#### HEMIST NOTES:

= sample was analyzed twice. The surrogate is high due to matrix interference.

08165

**ENVIROTECH INC.**

5796 U.S. Highway 64  
Farmington, New Mexico 87401  
(505) 632-0615