5-USGS 1-Lively	I-Shryack I-EPNG (UTTFIC	in) TEPNG (Texas)	1-000000 1-11	, <b>.</b>	
Form 9-331 (May 1963)	UNITED STATES PARTMENT OF THE INTERIO	SUBMIT IN TRIPLICATE* OR (Other instructions on re-	Form approved.  Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO.		
	GEOLOGICAL SURVEY		SF 078415A /		
SUNDRY (Do not use this form to Use	NOTICES AND REPORTS Of proposals to drill or to deepen or plug bandpulication for PERMIT—" for such pro	N WELLS ck to a different reservoir.	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
OIL GAS WELL WELL	OTHER		7. UNIT AGREEMENT NAM	í E	
2. NAME OF OPERATOR			8. FARM OR LEASE NAME		
Lively Exploration Company			Lively		
3. ADDRESS OF OPERATOR			9. WELL NO.		
Box 234, Farming	ton, New Mexico 87401	tota requirements	3 10. FIELD AND POOL, OR	WILDCAT	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface			Basin Dakota		
1080' FSL, 1500' FWL			11. SEC., T., R., M., OR BLK. AND		
1000 F3E, 1000 FME			SURVEY OR AREA		
			Sec. 9, T29N	<u> </u>	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, OR, etc.)	12. COUNTY OR PARISH		
	6495 GR		San Juan	N.M.	
16. Ci	neck Appropriate Box To Indicate No	ature of Notice, Report, or O	ther Data		
NOTICE	OF INTENTION TO:	SUBSEQU	ENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	ELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	BING	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN	T*	
REPAIR WELL	CHANGE PLANS	(Other)(Nore: Report results	of multiple completion o	n Well	
(Other)	LETED OPERATIONS (Clearly state all pertinent	Completion or Recomple	etion Report and Log form	m.)	
1-10-73	T.D. 7684. Ran 241 Jts CF&I casing. T.E. 7691.3 sacks 40-60 with ½% flost salt per sack, 660 cu. from ting. Maximum cement turns 66-75 bbls displace mainder of 122.6 bbls displace acetic acid. P.O.B. II: a.m. till complete. Rigg 3/4 hrs circulate - 1 hr 4½" casing, set at 7684 hrs pick up B.O.P. and sorigging down.	30' set at 7684' RKB. eat per sack and 100 t. sturry. Worked ca ing pressure 1700 psi ement in. Regained f splacement. Followed 50 a.m. 1-9-73. Good ging down and getting rig up to run 4½" ca - 1½ hrs cementing,	Cemented with sacks Class "Cosing okay while is Lost partia full returns for diplug with 300 diplug with 300 diplug ready to move using — 5 hrs refull returns —	h 150 " 7½# e ce- l re- gals 5:00 un	
18. I hereby certify that the fo		сом. /			
SULVENIE	ON Dy I. A. Dugan mirror	Engineer	DATE2-8-	73	
Thomas (This space for Federal or	A. Dugan				
APPROVED BYCONDITIONS OF APPROV	YAL, IF ANY:		DATE		