UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Carte to State

-	Budget Bureau No. 42-R1424
	5. LEASE \$ 5. SF _ 078416-A
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
nt	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME
	HARDIE
	9. WELL NO.
	3A
	10. FIELD OR WILDCAT NAME
	BLANCO MV -
7	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 25, T-29-N, R-8-W
	12. COUNTY OR PARISH 13. STATE
	SAN JUAN NEW MEXICO
Ξ,	14. API NO.
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6304' GL

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a differe reservoir. Use Form 9–331–C for such proposals.) gas well well other 2. NAME OF OPERATOR EL PASO NATURAL GAS CO. 3. ADDRESS OF OPERATOR BOX 990, FARMINGTON, NEW MEXICO 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1 below.) AT SURFACE: 1770'S, 990'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multiple completion or zone PULL OR ALTER CASING change on Form 9-330.) MULTIPLE COMPLETE **CHANGE ZONES** ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 9/18/78: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 32.3# H-40 surface casing, 203' set at 216'. Cemented with 224 cu. ft. cement. Circulated to surface. 12 hours; held 600#/30 minutes. Subsurface Safety Valve: Manu. and Type __ 18. I hereby certify that the foregoing is true and correct _ TITLE Drilling Clerk ___ DATE _9/19/78 SIGNED (This space for Federal or State office use)

APPROVED BY _ TITLE _ DATE CONDITIONS OF APPROVAL, IF ANY: