Dec. 1973	Form Approved. Budget Bureau No. 42–R1424					
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF - 078502					
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME					
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME					
eservoir. Use Form 9–331–C for such proposals.) 1. oil gas y	8. FARM OR LEASE NAME Vanderwart					
well well other	9. WELL NO.					
2. NAME OF OPERATOR Tenneco Oil Company	10. FIELD OR WILDCAT NAME					
3. ADDRESS OF OPERATOR	Basin Dakota					
720 S. Colo. Blvd., Denver, CO 80222	11. SEC., T., R., M., OR BLK. AND SURVEY OR					
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 11; T29N; R8W					
AT SURFACE: 10/5 FAL, 810 GEL	12. COUNTY OR PARISH 13. STATE					
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico					
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.					
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DE, KDB, AND WD)					
DEGUEST FOR APPROVAL TO: OURSESSIES POR	6324 'GL					
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF THE STREET WATER SHUT-OFF						
DACTURE TREAT						
RACTURE TREAT HOOT OR ACIDIZE REPAIR WELL 1380	EY (NOTE: Report results of multiple completion or zone change on Form 9–330.)					
ULL OR ALTER CASING	change on Form 9–330.)					
MULTIPLE COMPLETE CHANGE ZONES BANDON* BARMINGTON FARMINGTON						
BANDON* Status Report: Drilling FARM						
outery						
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di 	e all pertinent details, and give pertinent dates,					
measured and true vertical depths for all markers and zones pertinen	it to this work.)*					
1/18/80-1/3/80						
Spudded 13 3/4" hole on 1/18/80. Ran 5 jts o	f 9 5/8", 36#csa & set @ 230'.					
Cmt. w/225 sxs regular w/2% CACL2. Circ. cmt	. to surface WOC 12 hrs. Test to					
600 PSI. Reduced hole to 8 3/4" & resumed dr or 7", 23# csg @ 3698'. Cmt w/590 sxs Dowlite	illing. Un 1724; ran & set 90 jts					
regular w/2% CACL2 Circ to surface WOC A bro						

regular w/2% CACL2. Circ to surface WOC 4 hrs. Tested to 800 PSI. Reduced hole to 6½" & drilled to TD of 7666' on 1/29. Ran & set 16 jts of 4½". 1135, & 79 jts of 4½", 10.5#csg w/liner @ 7664', TOC: 3519. Cmt w/425 sxs. 50/59 Peznix, 4% get, .7% Halad-G, .7% CFR-2. Circ to surfact. Released rig 1/28/8

Subsurface Safety Valve: Manu. an			() () () () () () () () () ()		1980 DM. /	Ft.
SIGNED Linky Man	TITLE Admin. Supervisor DAT	TE	1/31/80			· .
	(This space for Federal or State office use)		필리하는데	: ≟	÷ , = 7	
APPROVED BY	TITLE D	DATE _	G : 4	<u> </u>	•	
CONDITIONS OF APPROVAL, IF ANY:	NMOCC.			170	1 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	