



Oklahoma City Division

Conoco Inc.
3817 Northwest Expressway
Oklahoma City, OK 73112-1400
(405) 948-3100

December 14, 1990

Oil Conservation Division
ATTN: Dorothy Jacquez
1000 Rio Brazos Road
Aztec, NM 87410

Dear Ms. Jacquez:

In filing of the Sundry Notices with the BLM, the pressure testing of the casing strings were inadvertently left off the notices. All future Sundry Notices will have the pressure testing information included. The following wells have the pressure information missing from the Sundry Notices:

Well #14 Day B
Lease #SF-078414
NE/4 Sec. 8-T29N-R8W

Well #4 Roelofs A
Lease #SF-078415
NE/4 Sec. 9-T29N-R8W

Well #8 Roelofs B
Lease #SF-078415
NE/4 Sec. 22-T29N-R8W

Well #13 Vandewart A
Lease #SF-078502
SW/4 Sec. 13-T29N-R8W

✓ Well #14 Vandewart A
Lease #SF-078502
NE/4 Sec. 14-T29N-R8W

Well #7 Roelofs B
Lease #SF-078415
SW/4 Sec. 15-T29N-R8W

Well #18 Hughes B
Lease #SF-078046
NE/4 Sec. 21-T29N-R8W

Well #11 Wilch A
Lease #SF-078416A
NE/4 Sec. 23-T29N-R8W

Well #12 Wilch A
Lease # SF-078416
SW/4 Sec. 23-T29N-R8W

Well #19 Hughes B
Lease #SF-078046
NE/4 Sec. 29-T29N-R8W

The pressure testing information is the same for the above wells. The surface casings (8 5/8") were tested to 1000 psi. for ten minutes and held. The production casings (5 1/2") were tested to 2600 psi. for 30 minutes and held.

I have attached nine copies of this letter one for each well folder. The well we are trying to expedite is the Roelofs B #7. If you have any questions or need additional information do not hesitate to give me a call at (405) 948-3234.

Gregory M. Gazda

Gregory M. Gazda
Staff Engineer, P.E.

GMG/083.wpd/sh

RECEIVED
DEC 26 1990
OIL CON. DIV.
DIST. 2