F. Loc. <u>1185/</u> Casing S. <u>@</u> Csg.Perf.	w [:]	Sx.	.π. Int		w	Cu. ft. Sx. Pr. Prod. Stim.	———@—		w	Cu. ft. Sx. T.		B @	7 Gas
P	After	Hrs.	SICP_	Р	SI After	Grav		1st De	i. <u>Gas</u>				A N S
IOPS		NITD		X	Well Log		TEST DAT						
Ojo Alamo		C-103			Plat	X	Schd.	PC	0	PW	PD	D	Ref.No.
Kirtland		C-104			Electric Log					 	 	-	K#1.190.
Fruitland					C-122					 	 	<u> </u>	
Pictured Cliffs		Ditr	· L		Día						 		
Chacra		Datr			Doc						ļ <u>.</u>		↓
Cliff House					1000								<u> </u>
Menefee				*						<u> </u>			
Point Lookout			.*				ļ <u>-</u>			ļ			
Mancos										 			
Gallup						Ì							<u> </u>
Greenhorn													ļ
Dakota													
Entrada													
												_	
					Ac	res 182.95		Į.					

BasinFrCoalCo. SJ S 06 7 29N R 08W U N Oper. Union Texas Petroleum Lee. Prichard Federal No. 7

Prichard Federal #7 N-06-29N-08W

UNION TEXAS PETROLEUM, INC.

MAR. 1 5 1991

CERTIFIED--RETURN RECEIPT REQUESTED P-338-000-292

Union Texas Petroleum, Inc. P.O. Box 2120 Houston, TX 77252-2120

MAR1 8 1991. OIL CON. DIV.

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 7 Prichard Federal, SE/4SW/4 sec. 6, T. 29 N., R. 8 W., San Juan County, New Mexico, lease SF-078487-B. As requested by your Sundry Notice dated February 5, 1991, the subject APD is rescinded and returned.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely.

Isl John L. Keller

John L. Keller Chief, Branch of Minerals

1 Enclosure

ce: New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION