

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)


Name of Company Pan American Petroleum Corporation		Address Box 487, Farmington, New Mexico			
Lease	Well No.	Unit Letter	Section	Township	Range
Valencia Gas Unit	1	J	18	T-29N	R-9W
Date well performed January 20, 1960	Pool Blanco Mesaverte		County San Juan		

THIS IS A REPORT OF: (Check appropriate block)

- | | | |
|--|--|---|
| <input type="checkbox"/> Beginning Drilling Operations | <input checked="" type="checkbox"/> Casing Test and Cement Job | <input type="checkbox"/> Other (Explain): |
| <input type="checkbox"/> Plugging | <input type="checkbox"/> Remedial Work | |

Detailed account of work done, nature and quantity of materials used, and results obtained.

On January 4, 1960, 7" casing was set at 2274' and cemented with 475 sacks 6% Gel and 2 lbs Tuf Plug per sack followed by 100 sacks neat cement. After waiting on cement, tested casing with 2200 pounds psi for 15 minutes with no indicated pressure drop. Reduced hole to 6-1/4" at 2275 and resumed drilling operations.



Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by Original Signed Emery C. Arnold		Name	ORIGINAL SIGNED BY R. M. Bauer, Jr.
Title Supervisor Dist. # 3		Position	
Date JAN 22 1960		Company	Area Engineer Pan American Petroleum Corporation

INVESTIGATION COMMISSION		
REPORT OF INVESTIGATION		
Case No. 4		
Subject		
Investigator	5	
Witness	1	
Interview Office		
Scene Investigation Office		
U. S. G. S.		
Transporter		
File	1	✓