TABULATION OF DEVIATION TESTS
PAN AMERICAN PETROLEUM CORPORATION

MYR GAS UNIT B NO. 1

· · · ·
DEVIATION
1/2° 1/2 3/4
3/4
1
1-3/4 1-1/4
1
1
1
1
1-1/2
2-3/4
1-1/2 2 2-3/4 3

AFFIDAVIT

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on PAN AMERICAN PETROLEUM CORPORATION'S By Gas Unit "B" No. 1, Basin Dakota Field, located in the SE/A NE/A of Section 7, T-29-N, H-9-W, Sen Juan County, Now Mexico.

Signed 7. 1. Hallugard L. Petroleum Engineer

THE STATE OF NEW MEXICO)
) SS.
COUNTY OF SAN JUAN
)

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said County and State this __lst. day of __Robress_______, 196#/5.

Notary Public