5. LEASE

UNITED STATES

DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR	SF 030246					
GEOLOGICAL SURVEY	6. 1	F INDIAN	I, ALLOTTEE	OR TRIE	E NAM	E
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. 1	_ UNIT AGF	REEMENT N	AME		
reservoir. Use Form 9–331–C for such proposals.)	8. 1	FARM OR	LEASE NAM	1E		
1. oil gas X other		Florance				
well Well Cother	1	WELL NO		_		
2. NAME OF OPERATOR Toppose Oil Company	<u>`</u>	57	WILDCATIN	IALE		
Tenneco Oil Company 3. ADDRESS OF OPERATOR	E	31anco	Picture	d Cli		
720 So. Colorado Blvd., Denver, CO. 80222	i	SEC., T., AREA	R., M., OR E	BLK. AND	SURVE	Y OR
4. LOCATION OF WELL (REPORT LOCATION CLEAFLY. See space 17 below.)			2, T-29 -	N. R-9)-W	
AT SURFACE: 1670' FNL & 1070' FEL, Unit H			OR PARISH			
AT TOP PROD. INTERVAL:		San Ju	an 🍦 🚊	New	Mexic	0.
AT TOTAL DEPTH:	14. /	API NO.	도 활의 등	÷	• • •	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
, and the second		7021 /	NS (SHOW GR	•	. ~	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) TO RESCRIPE PROPOSED OR COMPLETED OBERATIONS (Clearly state)			_ = = <u> </u>			
TEST WATER SHUT-OFF	-	i a t	2 () () () () () () () () () (
SHOOT OR ACIDIZE		Esser	4 2 1 2 2	를 <u>-</u>		
REPAIR WELL	wed	E: Report	results of mu	iltiple com	pletion o	r zone
PULL OR ALTER CASING	<u>ئ</u> ر	Chaus.	on form 9	33U.) - <u>-</u>	1 3 E	5
CHANGE ZONES	Sello-	♥. :		3 3	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	≘
ABANDON*	íst. 3	3			. 출하다 - 프라	311
(other)	10	:	<u> </u>	Ţ		8
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent 5/30/79 MIRUPU. NUBOP. Ran 73 jts 1½", 2.4# EUE tbg "B" cement from 1678'-2352'. Squeezed Pictur P & A'd well w/cement plugs @ the following d	t to 2	ally drilles work.)* 2352'. liffs	ed, give subsequences	surface le	ocations	and
1038' ~ 1678' (25 Sx)				2 4	4 E 2	
394' - 1038' (25 Sx)					, C. C.	
Surface- 394' (12 Sx)			e de don vicul p by	§ ≠ 3 ≠	1	
Cut off wellhead l' below grade & installed P	2. Δ	marke	r Will	clear	- & - I	
restore location per U.S.G.S. requirements as						
				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7 4 3	
Subsurface Safety Valve: Manu. and Type			=Set (@	<u> </u>	Ft.
18. Thereby certify that the foregoing is true and correct				ر ت ج		
SIGNED Chrilly Visition TITLE Admin. Supervi	sor ,	DATE	610	[2]	9	
(This space for Fr Seral or State office	e use)	DATE _	APP	RO	VE	: D
CONDITIONS OF APPROVAL IF ANY:		₹.	100 M	<u> 30</u>	1984	 پارگر ې
*See Instructions on Reverse Side			M. MILLENBACH AREA MANAGER			