TABULATION OF DEVIATION TESTS

TENNECO OIL COMPANY

FLORANCE #85

DEPTH	INCLINATION
127' 572' 1161' 1409' 1942' 2523'	1/4° 3/4° 1/4° 1/2° 3/4°

AFFIDAVIT

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on TENNECO OIL COMPANY'S FLORANCE #85, Blanco Pictured Cliffs Field, located in Section 23, T-29-N, R-9-W, San Juan County, New Mexico.

THE STATE OF COLORADO) COUNTY OF LA PLATA

BEFORE ME, the undersigned authority, on this day personally appeared Harold C. Nichols known to me to be Senior Production Clerk for Tenneco Oil Company and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said Count

this 9th day of May, 1966.

My commission expires June 28, 1969.

Distribution:

1 copy - New Mexico Oil Conservation Commission

1 copy - Continental

1 conv - File