

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-10424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 080000-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-----

7. UNIT AGREEMENT NAME

None

8. FARM OR LEASE NAME

Simmons - P.C.

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Blanco - P.C.

11. SEC., T., R., M., OR BLK. AND

Sec. 23 - T29N - R9W

N.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

N.M.

1.

OIL ☐ GAS ☒ OTHER ☐

2. NAME OF OPERATOR

D. J. Simmons, et al

3. ADDRESS OF OPERATOR

3815 McCart Street  
Fort Worth, Texas 76110

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

1550' FNL - 920' FWL  
Section 23 - T29N - R9W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5792 GR 5802 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) Well status & future plans ☒

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

At the present time the above captioned well is shut-in. In view of the previous attempt to squeeze off the rather wide interval of corrosion leaks without successful results and at extensive cost; also since a similar well with similar problems in sec. 22 of T29N-R9W has had extensive remedial work without success, it is requested that permission be granted to plug and abandon the above captioned well within 120 days depending on rig availability. The plugging & abandonment program shall be submitted for approval previous to commencement of operations.

18. I hereby certify that the foregoing is true and correct

SIGNED

Ashton B. Geren, Jr.

Manager & Supt. for:

TITLE D.J. Simmons

DATE Feb. 9, 1979

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: