

New Mexico Oil Conservation Commission  
1000 Rio Brazos Road  
Aztec, New Mexico

Re: ~~Mrs.~~ D. J. Simmons  
Simmons "E" - No. 2A  
1700' FNL - 790' FWL  
Sec. 23 - T29N - R9W  
San Juan Co., New Mexico

This is to certify that deviation tests were run on the  
above well and the following is a true report of these tests.

1/4 degree	at	568'
1/4 degree	at	1100'
1/2 degree	at	1656'
1/2 degree	at	2112'
1 1/4 degree	at	3146'
1 degree	at	3625'
1 degree	at	4194'
1 1/2 degree	at	4875'


Ashton B. Geren, Jr.  
Ashton B. Geren, Jr.  
Manager & Supt. for:  
Mrs. D. J. Simmons, Opr.

State of New Mexico                      )ss  
San Juan County

Subscribed and sworn to before me this 15th day of February, 1978.

My Commission expires: 7-9-79

Roberta N. Paschall  
Notary Public



1. The first part of the report is a general introduction to the subject of the study. It is followed by a brief review of the literature on the subject.

2. The second part of the report is a description of the methods used in the study. This includes a description of the subjects, the materials, and the procedures.

3. The third part of the report is a presentation of the results of the study. This includes a description of the data and a discussion of the findings.

1	10	1	1
2	10	1	1
3	10	1	1
4	10	1	1
5	10	1	1
6	10	1	1
7	10	1	1
8	10	1	1
9	10	1	1
10	10	1	1

4. The fourth part of the report is a discussion of the results of the study. This includes a discussion of the implications of the findings and a conclusion.

5. The fifth part of the report is a list of references. This includes a list of the books, articles, and other sources used in the study.

6. The sixth part of the report is a list of appendices. This includes a list of the tables, figures, and other materials that are included in the report.

7. The seventh part of the report is a list of footnotes. This includes a list of the footnotes that are included in the report.